

The KENWOOD DK-520 Digital Adaptor Kit is designed for adapting the DG-5 digital counter to the TS-520. The DK-520 consists mainly of a power supply with connectors to supply the signals to the DG-5, and a buffer unit for the HET output signals.

PARTS SUPPLIED

. NG 1997

1.	Power supply unit .		1
2.	Buffer unit		1
3.	Power cable		1
4.	Fuse, 2A		1
	Converter cover		
6.	Mounting stud		1
7.	Hardware:	- 2 D	·
÷.	a. panhead screw	Ix6 mm long	1
	b. self tapping scre	ws, 3x6 mm long	2
	c. lock washer .		1
*	d. flat washer		1
			1.8

INSTALLATION

First, remove the top and bottom covers of the TS-520. When removing the top cover, remember to unplug the speaker lead before setting the top aside. Install the DK-520 as follows: (Ref. to fig. 1 thru. 6)

- Y. Remove the wing nut and washer from the ground lug on the rear panel of the TS-520, and install the mountjng stud on the ground lug.
- Install the DK-520 power supply unit on the mounting stud as shown in fig. 1. Use the panhead screw, lock washer, and flat washer to hold the power supply unit jn place.
- S.Remove the slotted cover from the DC-DC converter.
- 4.Install the new slotted cover with the notch at the bottom.
- ✓ 5.Insert the wiring harness through the notch and feed it over the power transformer.
 - CLocate the DC-DC converter terminal board (See fig. 2).
 - Solder one of the two white solid wires from the power supply unit to the terminal with the red lead on it.
- Solder the other white solid wire to the terminal with the orange lead on it.
- Solder the black solid wire to the chassis ground lug (See fig. 2)
- CLocate the coaxial lead with the red band.
- **M**.Solder the center conductor of this cable to pin 1 of the remote VFO socket. (See fig. 2.)
- 2. Solder the shield of this cable to pin 2.

- A.Locate the cable harness that runs parallel to the front of the RF unit.
- Gently move this harness aside to reveal the two mountjing holes for the buffer unit.
- 15. Install the buffer unit with the two self tapping screws.
- 16.Solder the yellow solid wire from the buffer unit to TP-3 on the RF unit.
- V.Locate the yellow solid wire with the cap and install it over the case of FET Q8 (3sk22).
- Solder the black solid wire from the buffer unit to the GND pin on the RF unit.
- **19**. Solder the red solid wire from the buffer unit to the 14 pin of the FIX CH. AVR Unit.
- 20. Locate the coaxial lead with the blue band.
- 21/Solder the center conductor of this cable to the OUT terminal of the buffer unit.
- 2, Solder the shield of this cable to the GND terminal.
- 23. Feed the remaining coaxial cable, red solid wire, and white/black solid wire through the chassis as shown in Fig. 2.
- 24. Solder the red solid wire to pin 5 of the power connector as shown in Fig. 3.
- 25. Solder the white/black solid wire to the chassis ground jug.
- 26. Solder the center conductor of the coaxial cable to the OUT terminal of the CAR unit.
- A.Solder the shield to the GND terminal.
- 26.Solder a jumper on the WWV/JJY switch as shown in fig. 4. Do not jumper the orange and purple wire.







HOW TO CHECK DK-520 OPERATION

- 1. Check all wiring to be sure that all leads are correctly installed.
- 2. Turn the TS-520 power on and measure the voltage at the two pin power connector of the power supply unit. The output voltage should be between 13.0VDC and 17.5VDC.
- 3. Install the DG-5 cables as shown in Fig. 5. Check for proper frequency as per DG-5 Operating Manual.

TOOLS REQUIRED

- 1. Soldering iron (not to exceed 45 watts).
- 2. Solder
- 3. Phillips screwdriver
- 4. Long nose pliers
- 5. VOM



1.

DC OPERATION

For DC operation of the TS-520 (with DK-520) and DG-5, it will be necessary to short pins 4 and 5 of the TS-520 DC power cable as shown in fig. 6.





© 8471 PRINTED INJAPAN B50-2555-00