# **\*TB 9-6625-2232-35**

# **DEPARTMENT OF THE ARMY TECHNICAL BULLETIN**

# CALIBRATION PROCEDURE FOR DIGITAL VOLTMETER HEWLETT-PACKARD, MODEL 3456A

Headquarters, Department of the Army, Washington, DC

15 November 2002

Approved for public release; distribution is unlimited

**REPORTING OF ERRORS AND RECOMMENDING IMPROVEMENTS** 

You can improve this manual. If you find any mistakes or if you know of a way to improve these procedures, please let us know. Mail your letter, DA Form 2028 (Recommended Changes to Publications and Blank Forms) directly to Commander, U.S. Army Aviation and Missile Command, ATTN: AMSAM-MMC-MA-NP, Redstone Arsenal, AL 35898-5000. A reply will be furnished to you. You may also provide DA Form 2028 information to AMCOM via e-mail, fax, or the World Wide Web. Our FAX number is: DSN 788-6546 or Commercial 256-842-6546. Our e-mail address is: <u>2028@redstone.army.mil</u>. Instructions for sending an electronic 2028 may be found at the back of this manual. For the World Wide Web, use: <u>https://amcom2028.redstone.army.mil</u>.

			Paragraph	Page
SECTION	I.	IDENTIFICATION AND DESCRIPTION		
		Test instrument identification	1	2
		Forms, records, and reports	2	2
		Calibration description	3	2
	II.	EQUIPMENT REQUIREMENTS		
		Equipment required	4	3
		Accessories required	5	3
	III.	CALIBRATION PROCESS		
		Preliminary instructions	6	4
		Equipment setup	7	4
		Dc voltage	8	5
		Resistance	9	6
		Ac voltage	10	8
		Final procedure	11	9

<sup>\*</sup>This bulletin supersedes TB 9-6625-2232-50, dated 26 March 1993.

# SECTION I IDENTIFICATION AND DESCRIPTION

**1. Test Instrument Identification.** This bulletin provides instructions for the calibration of Digital Voltmeter, Hewlett-Packard, Model 3456A. The manufacturer's manual was used as the prime data source in compiling these instructions. The equipment being calibrated will be referred to as the TI (test instrument) throughout this bulletin.

#### a. Model Variations. None.

**b. Time and Technique**. The time required for this calibration is approximately 2 hours using the dc and low frequency technique.

#### 2. Forms, Records, and Reports

**a**. Forms, records, and reports required for calibration personnel at all levels are prescribed by TB 750-25.

**b**. Adjustments to be reported are designated (R) at the end of the sentence in which they appear. When adjustments are in tables, the (R) follows the designated adjustment. Report only those adjustments made and designated with (R).

**3. Calibration Description.** TI parameters and performance specifications which pertain to this calibration are listed in table 1.

Test instrument				sonption				
parameters	Performance specifications							
Dc voltage	Range: 0 to 1000 V (in 5 ranges)							
	Accuracy: ±(%	Accuracy: $\pm$ (% of reading + number of counts) <sup>1</sup>						
		Range						
		0.	1	0.0112	+	24		
		1.	0	0.0102	+	4		
		10.	0	0.0101	+	2		
		100.	0	0.0104	+	3		
		1000.0		0.0222	+	2		
Resistance	Range: $0\Omega$ to 1 G $\Omega$ (in 8 ranges)							
	Accuracy: ±(%	Accuracy: $\pm$ (% of reading + number of counts) <sup>2</sup>						
		Range						
		100	Ω	0.0092	+	24		
		1	kΩ	0.0082	+	4		
		10	kΩ	0.0082	+	4		
		100	kΩ	0.0082	+	2		
		1	MΩ	0.0122	+	2		
		10	MΩ	0.0472	+	2		
		100	MΩ	1.8052	+	1		
		1	GΩ	16.0052	+	1		

Table 1. Calibration Description

See footnotes at end of table.

Test instrument					•					
parameters		Performance specifications								
Ac voltage	Ran	ge: 0 to	700 V I	rms (ii	n 4 range	s)				
	Accu	aracy: ±	(% of re	ading	+ numbe	r of coun	ts) <sup>3</sup>			
	Frequencies									
	20 to 30 Hz 0.402 + 6					656				
		30	Hz	to	20	kHz	0.122	+	856	
		20		to	50	kHz	0.222	+	1856	
		50		to	100	kHz	0.602	+	3056	
		100		to	250	kHz	5.052	+	6656	

Table 1. Calibration Description - Continued

<sup>1</sup>AUTO ZERO pushbutton on, FILTER off, and 10 PLC.

<sup>2</sup>AUTO ZERO pushbutton on, FILTER off, 10 PLC, and 4 WRΩ (add 0.2Ω offset for 2 WRΩ measurements).
<sup>3</sup>AUTO ZERO pushbutton on, FILTER on, 10 PLC, >1% of FS, and dc component <10% of ac (for inputs >500 V rms add 0.07% of reading). Frequencies >100 kHz are specified for 1 V and 10 V ranges only.

# SECTION II EQUIPMENT REQUIREMENTS

**4. Equipment Required.** Table 2 identifies the specific equipment to be used in this calibration procedure. This equipment is issued with Secondary Transfer Standards Set AN/GSM-286. Alternate items may be used by the calibrating activity. The items selected must be verified to perform satisfactorily prior to use and must bear evidence of current calibration. The equipment must meet or exceed the minimum use specifications listed in table 2.

**5.** Accessories **Required.** The accessories required for this calibration are common usage accessories, issued as indicated in paragraph **4** above, and are not listed in this calibration procedure.

						cturer a	and model	
Common name	Mi		(part number)					
CALIBRATOR	Dc voltage	e: Accu	uracy: (±%)		John Fluke, Model 5720A			
	100 mV	0.	0034		(p/o MIS-35947); w/power			
	1 V	0.	00265		amplifier, J	ohn Flu	ıke Model	
	10 V	0.	002575		5725A (572	5A)		
	100 V	0.	002675					
	1000 V	0.	0056					
	Ac voltage ra	Ac voltage range: 1 to 700 V						
	Frequenc	equency: 25 Hz to 250 kHz						
	Accuracy:	(±%)						
			]	Frequency	y (kHz)			
	Ac voltage	0.025 1 45		45	9	5	250	
	1 V	0.1169 0.0519 0.101			9 0.22	269	1.4294	
	10 V			0.1019	9 0.22	269	1.4294	
	100 V			0.1019	9 0.22	269		
	700 V		0.0786	0.1393	3 0.27	71		

Table 2. Minimum Specifications of Equipment Required

	•	••	Manufacturer and model
Common name	Minimum	use specifications	(part number)
CALIBRATOR - continued	Resistance $(\Omega)$	Accuracy: (±%)	John Fluke, Model 5720A
	100	0.0029	(p/o MIS-35947); w/power
	1 k	0.00215	amplifier, John Fluke Model
	10 k	0.00215	5725A (5725A)
	100 k	0.0021	
	1 M	0.0031	
	10 M	0.0118	
RESISTANCE	Resistance:	Accuracy: (±%)	Beckman, Model CR1000M
STANDARD	100 MΩ	0.4513	(8579478)
	1000 MΩ	4	

Table 2. Minimum Specifications of Equipment Required - Continued

# SECTION III CALIBRATION PROCESS

#### 6. Preliminary Instructions

**a**. The instructions outlined in paragraphs **6** and **7** are preparatory to the calibration process. Personnel should become familiar with the entire bulletin before beginning the calibration.

**b**. Items of equipment used in this procedure are referenced within the text by common name as listed in table 2.

**c**. Unless otherwise specified, verify the results of each test and, whenever the test requirement is not met, take corrective action before continuing with the calibration. Additional maintenance information is contained in the manufacturer's manual for this TI.

**d**. Unless otherwise specified, all controls and control settings refer to the TI.

## 7. Equipment Setup

#### WARNING

HIGH VOLTAGE is used or exposed during the performance of this calibration. DEATH ON CONTACT may result if personnel fail to observe safety precautions. REDUCE OUTPUT(s) to minimum after each step within the performance check where applicable.

- **a**. Connect TI to a 115 V ac power source.
- **b**. Press **LINE OFF/ON** pushbutton to **ON** and allow at least 1 hour for warm up.
- c. Ensure TI input terminals are not connected to any external circuitry.

# d. Release **TERMINALS FRONT/REAR** pushbutton out to **FRONT** and press **GUARD (FRONT TERM) OPEN/TO LO** pushbutton in to **TO LO**.

e. Press TEST key.

#### NOTE

Once the test is completed, the display and LEDs go blank for a time and the operation starts again. If any of the internal checks do not pass, a negative integer corresponding to the check which did not pass is displayed. Refer to the manufacturer's manual if the internal test does not pass.

f. Press **TEST** key again upon completion of a test.

#### 8. DC Voltage

#### a. Performance Check

- (1) Connect calibrator OUTPUT HI and LO to TI VOLTS/2WRW/4WRW HI and
- LO.
- (2) Press keys as listed in (a) through (d) below:
  - (a) **RESET**.
  - (b) MATH/REGISTERS 6.
  - (c) MATH/REGISTERS STORE.
  - (d) MATH/REGISTERS 9/N DIG DISP.

(3) Set calibrator output to settings listed in table 3. If TI does not indicate within limits specified, perform **b** below.

Table 5. DC Voltage								
Calibrator	Test ins	trument						
output	indic	ations						
settings	Min	Max						
100 mV	99.9864 -3	100.0136 -3						
1 V	.999894	1.000106						
10 V	9.99897	10.00103						
100 V	99.9893	100.0107						
1000 V	99.776	1000.224						

Table 3. Dc Voltage

#### **b.** Adjustments

#### NOTE

Adjustments are located behind a front panel section located at the front input terminals.

- (1) Set calibrator for a 10 V output.
- (2) Adjust **A** (coarse) and **B** (fine) until TI indicates 10.00000 ±1 count (R).
- (3) Set calibrator for a 1 V output.

- (4) Adjust **C** until TI indicates 1.000000 ±l count (R).
- (5) Set calibrator to **STANDBY** and disconnect from TI.
- (6) Press **RANGE B** key to 100 mV range.
- (7) Short **VOLTS/2WRW/4WRW HI** and **LO** using copper wire or shorting bar.

# (8) Press MATH/REGISTERS MATH key then press MATH/REGISTERS 3/NULL key.

- (9) Remove short from **VOLTS/2WRW/4WRW HI** and **LO**.
- (10) Connect calibrator OUTPUT HI and LO to TI VOLTS/2WRW/4WRW HI and

## **LO**.

- (11) Set calibrator for a 100 mV output.
- (12) Adjust **D** until TI indicates 100.0000 -3 ±5 counts (R).
- (13) Press keys as listed in (a) through (f) below:
  - (a) MATH/REGISTERS MATH.
  - (b) MATH/REGISTERS 0/OFF.
  - (c) **RANGE Ý** to 100 V range.
  - (d) MATH/REGISTERS 6.
  - (e) MATH/REGISTERS STORE.
  - (f) MATH/REGISTERS 9/N DIG DISP.
- (14) Set calibrator for a 100 V output.
- (15) Adjust **E** until TI indicates 100.0000 ±1 count (R).

# 9. Resistance

# a. Performance Check

- (1) Connect calibrator **OUTPUT HI** and **LO** to TI **VOLTS/2WRW/4WRW HI** and
- LO.

(2) Connect calibrator **SENSE HI** and **LO** to TI **RATIO REF/4WRW SENSE HI** and **LO**.

- (3) Press keys as listed in (a) through (e) below:
  - (a) **RESET**.
  - (b) **MATH/REGISTERS 6**.
  - (c) MATH/REGISTERS STORE.
  - (d) MATH/REGISTERS 9/N DIG DISP.
  - (e) **FUNCTION 4 WrW**.

(4) Set calibrator for a  $\Omega$  output and **EX SNS** on. TI will indicate between -00.0024 and 00.0024.

(5) Set calibrator output for settings listed in table 4. At each output setting, use calibrator output adjustment controls to set calibrator control display **Reading** equal to TI indication. **I** calibrator control display **Error** indications are not within limits specified, perform **b** below.

Table 4. Resistance						
Cali	Calibrator					
Output settings	Control display Error					
(Ω)	indications (±%)					
100	0.0116					
1 k	0.0086					
10 k	0.0086					
100 k	0.0084					
1 M	0.0124					
10 M	0.0474					

(6) Disconnect calibrator from TI.

(7) Connect TI **RATIO REF/4WRW SENSE** and **VOLTS/2WRW/4WRW HI** and **LO** to resistance standard for 100 M $\Omega$ . TI will indicate between 98.1947 +6 and 101.8053 +6.

(8) Connect TI **RATIO REF/4WRW SENSE** and **VOLTS/2WRW/4WRW HI** and **LO** to resistance standard for 1000 M $\Omega$ . TI will indicate between 839.947 +6 and 1160.053 +6.

(9) Press TI **FUNCTION 2 WrW** key. TI will indicate between 839.947 +6 and 1160.053 +6.

# b. Adjustments.

#### NOTE

Adjustments are located behind a front panel section located at the front input terminals.

(1) Set calibrator for a 10 k $\Omega$  output. Adjust **F** until TI indication is within ±1 count of calibrator output display indication rounded to TI digits of resolution.

(2) Set calibrator for a 1 k $\Omega$  output. Adjust **G** until TI indication is within ±1 count of calibrator output display indication rounded to TI digits of resolution.

(3) Set calibrator for a 100 k $\Omega$  output. Adjust **H** until TI indication is within ±1 count of calibrator output display indication rounded to TI digits of resolution.

(4) Set calibrator for a 1 M $\Omega$  output. Adjust **I** until TI indication is within ±1 count of calibrator output display indication rounded to TI digits of resolution.

(5) Set calibrator for a 10 M $\Omega$  output. Adjust **J** until TI indication is within ±4 counts of calibrator output display indication rounded to TI digits of resolution.

#### **10. Ac Voltage**

#### a. Performance Check

- (1) Connect calibrator **OUTPUT HI** and **LO** to TI **VOLTS/2WRW/4WRW HI** and
- **LO**.
- (2) Press keys as listed in (a) through (f) below:
  - (a) **RESET**.
  - (b) **FUNCTION** ~**V**.
  - (c) **FILTER** to on.
  - (d) MATH/REGISTERS 6.
  - (e) MATH/REGISTERS STORE.
  - (f) MATH/REGISTERS 9/N DIG DISP.

(3) Set calibrator to settings listed in table 5. If TI indications are not within limits specified, perform **b** below.

		Table 5. A	Ac Voltage	
Calibrator ou	Calibrator output settings			nt indications
Voltage (V)	Free	luency	Min	Max
1	25	Hz	0.995324	1.004676
1	1	kHz	0.997924	1.002076
1	45	kHz	0.995924	1.004076
1	95	kHz	0.990924	1.009076
1	250	kHz	0.942824	1.057176
10	25	Hz	9.95324	10.04676
10	1	kHz	9.97924	10.02076
10	45	kHz	9.95924	10.04076
10	95	kHz	9.90924	10.09076
10	250	kHz	9.42824	10.57176
100	25	Hz	99.5324	100.4676
100	1	kHz	99.7924	100.2076
100	45	kHz	99.5924	100.4076
100	95	kHz	99.0924	100.9076
700	1	kHz	697.8	702.2
700	45	kHz	696.1	703.9
700	95	kHz	692.24	707.76

## **b.** Adjustments

#### NOTE

Adjustments are located behind a front panel section located at the front input terminals.

(1) Set calibrator to **STANDBY**.

(2) Press TI **RESET** key then **FUNCTION** ~**V** key.

(3) Set calibrator for a 1 V, 1 kHz output.

(4) Press TI **RANGE Ý** or **B** key to 100 V range. Adjust **K** until TI indicates  $01.000 \pm 1 \text{ count (R)}$ .

(5) Press TI  ${\bf RANGE}\ {\bf B}$  key to 1 V range. Adjust  ${\bf L}$  until TI indicates 1.00000 ±3 counts (R).

(6) Press TI **RANGE Ý** key to 1 kV range. Adjust either **M** or **N** until TI indicates  $001.00 \pm 2$  counts (R).

(7) Repeat (4) through (6) above until no further adjustments are necessary.

(8) Set calibrator to **STANDBY** and disconnect from TI.

(9) Short TI **VOLTS/2WRW/4WRW HI** and **LO**.

(10) Press **FUNCTION** ~ + = key and **RANGE Ý** or **B** key to 1 V range. Adjust **N** for a minimum TI indication.

(11) Press **FUNCTION** ~**V** key and perform (a) through (c) below:

- (a) Record TI indication.
- (b) Adjust **M** for a minimum TI indication.

(c) Continue adjusting  ${\bf M}$  in the same direction until TI indication is within  $\pm 2$  counts of indication recorded in (a) above.

(12) Repeat (10) and (11) above until both indications are within  $\pm 2$  counts of each other.

# **11. Final Procedure**

**a**. Deenergize and disconnect all equipment.

**b**. Annotate and affix DA label/form in accordance with TB 750-25.

#### **THESE ARE THE INSTRUCTIONS FOR SENDING AN ELECTRONIC 2028**

The following format must be used if submitting an electronic 2028. The subject line must be exactly the same and all fields must be included; however, only the following fields are mandatory: 1, 3, 4, 5, 6, 7, 8, 9, 10, 13, 15, 16, 17, and 27.

From: "Whomever" whomever@avma27.army.mil To: 2028@redstone.army.mil Subject: DA Form 2028 1. **From**: Joe Smith 2. Unit: Home 3. Address: 4300 Park 4. City: Hometown 5. St: MO 6. **Zip**: 77777 7. Date Sent: 19-Oct-93 8. Pub No: TB 9-6625-xxxx-35 9. Pub Title: Calibration Procedure for ... 10. **Publication Date**: 11. Change Number: 12. Submitted Rank: MSG 13. Sumitter Fname: Joe 14. Submitter Mname: T 15. Submitter Lname: Smith 16. Submitter Phone: (123) 123-1234 17. **Problem**: 1 18. Page: 2 19. Paragraph: 3 20 Line: 4 21. NSN: 5 22. Reference: 6 23. Figure : 7 24. Table: 8 25. Item: 9 26. Total: 123 27: **Text**:

This is the text for the problem below line 27.

By Order of the Secretary of the Army:

ERIC K. SHINSEKI General, United States Army Chief of Staff

OFFICIAL:

Joel B. Hula

JOEL B. HUDSON Administrative Assistant to the Secretary of the Army 0227706

Distribution:

To be distributed in accordance with initial distribution number (IDN) 344753, requirement for calibration procedure TB 9-6625-2232-35.