

Errata Sheet of Rev. B PIC16C62 Silicon

The PIC16C62 (Rev. B) parts you have received conform functionally to the upcoming PIC16C6X preliminary data sheet (DS30234B), except for the anomalies described below.

All the problems listed here will be addressed in the future revisions of the PIC16C62 silicon.

1. When using the SPI (SSP module), the master mode with clock = OSC/64 does not function correctly (at any voltage).
2. When using the I²C™ (SSP module), in the master mode, the TRISC<4:3> bits will NOT manipulate the corresponding SCL and SDA pins. Note that in slave mode the device will drive out the proper levels.

Work-around:

For the SDA pin.

To control the level of the SDA pin, connect an additional I/O pin to the SDA pin. Use this additional I/O pin to control the output for the master data (via the TRIS and PORT bits of that pin). Note that since a general purpose I/O pin is now controlling the output data, the SDA will not have slope control.

For the SCL pin.

To control the level of the SCL pin, use the CKP bit (SSPCON<4>). The SCL pin will continue to have slope control.

CKP = 0 will force the SCL line low.

CKP = 1 will enable the SCL line to be pulled high (via the external pull-up).

3. When the Timer1 counter uses the external oscillator (T1OSCEN is set), the Timer1 counter may increment faster than expected. This occurs because the OSC2/CLKOUT output signal may be coupled into the T1CKI input, giving additional clock pulses. When the device is in sleep the Timer1 counter increments correctly. This is because the device's oscillator is turned off. If the T1CKI is driven with an external clock (with reasonable drive capability), the OSC2/CLKOUT signal will not be coupled into the T1CKI pin. This will allow the Timer1 counter to increment at the expected frequency.
4. When the Timer1 oscillator circuit is used (enabled and oscillating), the digital input buffers are not disabled. This causes the device to have a greater than expected current consumption in both normal operation and sleep mode.
5. When the SSP module is programmed for any I²C mode, but the SSP module is disabled (SSPEN is cleared), unexpected data may be driven from the SCK pin. This occurs when the CKP bit (SSPCON<4>) is cleared, which then drives the value of PORTC<3>.

Work-around:

When disabling the SSP module, ensure that the CKP bit is set or that the SSP module is not in any I²C mode.

6. The internal Power-On Reset pulse may not generate the power-up timer, time-out delay. This means that the EPROM could be accessed before the device reaches a valid operational V_{DD} voltage. The master clear ($\overline{MCLR}$) pin should be held at low level (device in reset), until a valid device V_{DD} operating voltage is reached.
7. When Timer1 is used with a synchronized external clock input ($T1CON<TMR1CS=1>$ and $T1CON<T1SYNC=0>$), unexpected operation may occur. The external clock is not guaranteed to be synchronized with internal phase clocks. This may result in missing or additional clocks on Timer1.
8. In the SPI Master mode, the use of TMR2 as the clock source will cause the SPI CLK pin to continuously output the clock pulses. These pulses will start once the mode is enabled and can only be disabled by changing the SPI mode or making the CLK pin an input.
9. When using the T1CKI pin as the clock source for Timer 1, care should be taken to ensure that the clock edge is "fast". In this mode, the input does not have a Schmitt Trigger input. This can cause the timer to increment several times if the clock edge is "slow" (and has some noise). The use of a "fast" clock edge, or an external Schmitt Trigger buffer to the clock edge is recommended. This is not an issue when Timer 1 uses an crystal with the internal oscillator circuit.
10. The $\overline{POR}$ bit in the PCON register is not guaranteed to be cleared on a power-up situation. It is recommended that this bit not be used to determine if a power-up had occurred.

Clarifications/Corrections to the Data Sheet:

In the PIC16C6X Preliminary Data Sheet (document DS30234B), the following clarifications and corrections should be noted.

1. The AC specifications are not yet implemented in the device test program. Characterization has shown a specification that may vary from the data sheet specification. This specification is shown in Table 1.
2. If peripherals on PORTC are operating, then read-modify-write instructions should not be used on the TRISC register. This could lead to an unexpected change of data direction on some PORTC pins. This is because the peripherals may temporarily override the data direction of the pin, and it may be this value that is read. Use of a TRISC shadow register is recommended, where all operations are applied to the shadow register. This shadow register then can be written to TRISC at any time.

3. In the PIC16C62 Product Brief (DS30414A), the pin-out of the SSOP package is wrong. The correct pin-out is shown in Figure 0-1.

FIGURE 0-1: NEW SSOP PIN-OUT




TABLE 1: AC SPECIFICATION LIMITS THAT VARY FROM DATA SHEET

Parameter No.	Sym.	Characteristic		Char. Data		Data Sheet		Units	Condition
				Min.	Max.	Min.	Max.		
73	TdiV2scH TdiV2scL	Setup time of SDI data input to SCK edge		Tosc	-	Tcy	-		
74	Tsch2dil TscL2dil	Hold time of SDI data input to SCK edge		Tosc	-	0.5 Tcy	-		
106	THD:DAT	Data Input Hold Time	100 kHz mode	20	-	0	-	ns	Automotive Temperature range
			400 kHz mode	0.02	0.9	0	0.9	us	

Note: As with any windowed EPROM device, please cover the window at all times, except when erasing.

WORLDWIDE SALES & SERVICE

AMERICAS

Corporate Office

Microchip Technology Inc.
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 602 786-7200 Fax: 602 786-7277
Technical Support: 602 786-7627
Web: <http://www.mchip.com/microchip>

Atlanta

Microchip Technology Inc.
500 Sugar Mill Road, Suite 200B
Atlanta, GA 30350
Tel: 770 640-0034 Fax: 770 640-0307

Boston

Microchip Technology Inc.
5 Mount Royal Avenue
Marlborough, MA 01752
Tel: 508 480-9990 Fax: 508 480-8575

Chicago

Microchip Technology Inc.
333 Pierce Road, Suite 180
Itasca, IL 60143
Tel: 708 285-0071 Fax: 708 285-0075

Dallas

Microchip Technology Inc.
14651 Dallas Parkway, Suite 816
Dallas, TX 75240-8809
Tel: 214 991-7177 Fax: 214 991-8588

Dayton

Microchip Technology Inc.
Suite 150
Two Prestige Place
Miamisburg, OH 45342
Tel: 513 291-1654 Fax: 513 291-9175

Los Angeles

Microchip Technology Inc.
18201 Von Karman, Suite 1090
Irvine, CA 92715
Tel: 714 263-1888 Fax: 714 263-1338

AMERICAS (continued)

New York

Microchip Technology Inc.
150 Motor Parkway, Suite 416
Hauppauge, NY 11788
Tel: 516 273-5305 Fax: 516 273-5335

San Jose

Microchip Technology Inc.
2107 North First Street, Suite 590
San Jose, CA 95131
Tel: 408 436-7950 Fax: 408 436-7955

CANADA

Microchip Technology Inc.
5925 Airport Road, Suite 200
Mississauga, Ontario L4V 1W1, Canada
Tel: 905 405-6279 Fax: 905 405-6253

ASIA/PACIFIC

Hong Kong

Microchip Technology
Unit No. 3002-3004, Tower 1
Metroplaza
223 Hing Fong Road
Kwai Fong, N.T. Hong Kong
Tel: 852 2 401 1200 Fax: 852 2 401 3431

Korea

Microchip Technology
168-1, Youngbo Bldg. 3 Floor
Samsung-Dong, Kangnam-Ku,
Seoul, Korea
Tel: 82 2 554 7200 Fax: 82 2 558 5934

Singapore

Microchip Technology
200 Middle Road
#10-03 Prime Centre
Singapore 188980
Tel: 65 334 8870 Fax: 65 334 8850

Taiwan

Microchip Technology
10F-1C 207
Tung Hua North Road
Taipei, Taiwan, ROC
Tel: 886 2 717 7175 Fax: 886 2 545 0139

EUROPE

United Kingdom

Arizona Microchip Technology Ltd.
Unit 6, The Courtyard
Meadow Bank, Furlong Road
Bourne End, Buckinghamshire SL8 5AJ
Tel: 44 1 628 850303 Fax: 44 1 628 850178

France

Arizona Microchip Technology SARL
Zone Industrielle de la Bonde
2 Rue du Buisson aux Fraises
91300 Massy - France
Tel: 33 1 69 53 63 20 Fax: 33 1 69 30 90 79

Germany

Arizona Microchip Technology GmbH
Gustav-Heinemann-Ring 125
D-81739 Muenchen, Germany
Tel: 49 89 627 144 0 Fax: 49 89 627 144 44

Italy

Arizona Microchip Technology SRL
Centro Direzionale Colleoni
Palazzo Taurus 1 V. Le Colleoni 1
20041 Agrate Brianza, Milan Italy
Tel: 39 39 689 9939 Fax: 39 39 689 9883

JAPAN

Microchip Technology Intl. Inc.
Benex S-1 6F
3-18-20, Shin Yokohama
Kohoku-Ku, Yokohama
Kanagawa 222 Japan
Tel: 81 45 471 6166 Fax: 81 45 471 6122

4/08/96



All rights reserved. © 1996, Microchip Technology Incorporated, USA.

Information contained in this publication regarding device applications and the like is intended through suggestion only and may be superseded by updates. No representation or warranty is given and no liability is assumed by Microchip Technology Incorporated with respect to the accuracy or use of such information, or infringement of patents or other intellectual property rights arising from such use or otherwise. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any intellectual property rights. The Microchip logo and name are registered trademarks of Microchip Technology Inc. All rights reserved. All other trademarks mentioned herein are the property of their respective companies.