

Errata Sheet for PIC17C42 Rev. C Silicon

The PIC17C42 (Rev. C) parts that you have received conform to the preliminary data sheet (DS30073C), except for the anomalies described below.

1. The Watchdog Timer (WDT) does not operate as documented for sleep mode, when the Oscillator Start-Up Timer (OST) is enabled (in LF or XT crystal mode). Regardless of the mode of the WDT (enabled or disabled), if the `SLEEP` instruction was executed when the WDT is greater than or equal to 50% of the time-out period, any interrupt that wakes the processor will cause a WDT reset.

Work-arounds

- a) For the case where the WDT is disabled. Before executing the `SLEEP` instruction, ensure that the WDT has timed-out. This can be done by monitoring the `TO` bit for when it goes from set to clear. Sample code for this test is shown below. The first bit test determines if the WDT has cleared the `TO` bit yet. If the `TO` bit is cleared, the state of the WDT is unknown and must be cleared. This sets the `TO` bit so the WDT roll-over can be observed.

```

      BTFSS  CPUSTA, TO   ; TO = 0?
      CLRWD  ; YES, WDT = 0
LOOP   BTFSC  CPUSTA, TO   ; WDT rollover?
      GOTO  LOOP          ; NO, wait
      SLEEP  ; YES, goto sleep

```

- b) For both the WDT enabled and disabled. Ensure that the `CLRWD` instruction is executed before the WDT increments past 50% of the WDT period.
- c) Use EC or RC oscillator modes

2. When the clock source of Timer1, Timer2, or Timer3 is selected to external clock, The overflow interrupt flag of the timer will be set twice. Once when the timer value equals the period register, and a second time when the timer value is reset to 0h (this is the correct flag). If the interrupt latency to clear the timer interrupt flag bit is greater than the time to the next timer clock pulse, no problems will be noticed. If the interrupt latency to clear the timer interrupt flag bit is less than the time to the next timer clock pulse, the interrupt will be serviced twice.

Work-arounds

- a) While in the Interrupt Service Routine, ensure that the timer has rolled over to 0h before clearing the flag bit.
- b) If the time before the next clock is great, have a flag bit which indicates that the Interrupt Service Routine should ignore the first occurrence of the timer interrupt.
- c) Clear the timer in software. Doing this causes the period to be one timer count less then expected.

Clarifications / Corrections to the Data Sheet

1. The XT and LF oscillator ranges have been respecified. The typical `IDD` curves will correlate to the devices if the new oscillator option is used for the desired frequency range. This is shown in Table 1.

TABLE 1: OSCILLATOR FREQUENCY OPTIONS

| Old Spec. | | New Spec. | | Oscillator Fuse Option |
|-----------|---------|-----------|--------|------------------------|
| Min | Max | Min | Max | |
| DC | 200 KHz | DC | 2 MHz | LF mode |
| 200 KHz | 25 MHz | 2 MHz | 25 MHz | XT mode |

AMERICAS

Corporate Office

Microchip Technology Inc.
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 602 786-7200 Fax: 602 899-9210

Atlanta

Microchip Technology Inc.
1521 Johnson Ferry Road NE, Suite 170
Marietta, GA 30062
Tel: 404 509-8800 Fax: 404 509-8600

Boston

Microchip Technology Inc.
Five The Mountain Road, Suite 120
Framingham, MA 01701
Tel: 508 820-3334 Fax: 508 820-4326

Chicago

Microchip Technology Inc.
665 Tollgate Road, Unit C
Elgin, IL 60123-9312
Tel: 708 741-0171 Fax: 708 741-0638

Dallas

Microchip Technology Inc.
17480 N Dallas Parkway, Suite 114
Dallas, TX 75287
Tel: 214 733-0391 Fax: 214 250-4631

Los Angeles

Microchip Technology Inc.
18201 Von Karman, Suite 455
Irvine, CA 92715
Tel: 714 263-1888 Fax: 714 263-1338

AMERICAS (continued)

New York

Microchip Technology Inc.
150 Motor Parkway, Suite 416
Hauppauge, NY 11788
Tel: 602 786-7200 Fax: 516 273-5335

San Jose

Microchip Technology Inc.
2107 N First Street, Suite 590
San Jose, CA 95131
Tel: 408 436-7950 Fax: 408 436-7955

ASIA/PACIFIC

Hong Kong

Microchip Technology Inc.
Unit No. 2520-2525
Tower 1, Metroplaza
Hing Fong Road, Kwai Fong
N.T., Hong Kong
Tel: 852 410 2715 Fax: 852 401 3431

Korea

Microchip Technology Korea
168-1, 2 Youngbo Bldg. 3 Floor
Samsung-Dong, Kangnam-Ku,
Seoul, Korea
Tel: 82 02 554 7200 Fax: 82 02 558 5934

EUROPE

United Kingdom

Arizona Microchip Technology Ltd.
Unit 6, The Courtyard
Meadow Bank, Furlong Road
Bourne End, Buckinghamshire SL8 5AJ
Tel: 44 0628 851 077 Fax: 44 0628 850 259

Germany

Arizona Microchip Technology GmbH
Alte Landstrasse 12-14
85521 Ottobrunn, Germany
Tel: 49 089 609 6072 Fax: 49 089 609 1997

France

Arizona Microchip Technology SARL
2, Rue Du Buisson aux Fraises
F-91300 Massy, France
Tel: 33 01 6953 6320 Fax: 33 01 6930 9309

Italy

Arizona Microchip Technology SARL
Centro Direzionale Colleoni
Palazzo Pegaso Ingresso No. 2
Vio Paracelso 23
Brienza (MI), Italy
Tel: 39 039 689 9933 Fax: 39 039 602 1585

JAPAN

Microchip Technology International Inc.
Shinyokohama Gotoh Bldg. 8F, 3-22-4
Shinyokohama, Kohoku-Ku, Yokohama-Shi
Kanagawa 222 Japan
Tel: 81 45 471-6166 Fax: 81 45 471-6122



MICROCHIP

Printed in USA 1994, Microchip Technology Incorporated. All Rights Reserved.

11/01/94

*Information contained in this publication regarding device applications and the like is intended by way of suggestion only. No representation of warranty is given and no liability is assumed by Microchip Technology Inc. with respect to the accuracy or use of such information. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. The Microchip logo and name are trademarks of Microchip Technology Incorporated. All rights reserved. All other trademarks mentioned herein are the property of their respective companies.