

3 Oak Park Bedford, MA 01730 Tel (781) 280-0300, Fax (781) 280-0499 email: csupport@lexicon.com

MPX G2 SERVICE BULLETIN

SUBJECT: The +5V regulator has been updated to a new part to improve thermal characteristics

REFERENCE: ECO 980925-00

DISTRIBUTION: International Distributor Service Centers, Customer Service and

Repair

CORRECTIVE ACTION: No field action; informational bulletin only U30 and U71, Lexicon Part Number 340-00742 IC,LINEAR,7805(LM340T-5) is replaced by Lexicon Part Number 340-13540 IC,LINEAR,LM2940C,5V REG,TO220. This change is effective with serial number: Lxxxx-1295. There is **no** requirement to update any existing product in the field.

EQUIPMENT REQUIRED: None

Please contact LEXICON CUSTOMER SERVICE with any questions.

Sbmpxg2_980925-00 Date: October 15, 1998

1