

TECHNICAL INFORMATION



No: 86/06/04/NAS
Ref:
Issue: 1
Date: 20 August 2004

Headlight Bulb Failure

AFFECTED VEHICLE RANGE:

Discovery Series II (LT)

3A767797 onwards

SITUATION:

PREMATURE HEADLIGHT BULB FAILURE

The customer may complain of a headlight bulb failure relatively early in the life of the vehicle.

RESOLUTION:

REPLACE BULBS WITH NEW LONG LIFE BULB

A long life service headlight bulb (XZQ000011) is now available from Land Rover Parts as a replacement bulb. Upon customer complaint of premature bulb failure, follow repair procedure below. If one bulb fails, all four bulbs must be replaced at the same time.

PARTS INFORMATION:

XZQ000011.....H7 headlight bulb Qty 4

DDW WARRANTY CLAIMS:

Information Only

*Normal warranty policy and procedures apply.
Material allowance is included in labor operation.*

REPAIR PROCEDURE

1. Remove and replace all 4 bulbs with long life service replacement bulb (XZQ000011)
2. Ensure the bulb access covers are correctly installed with the arrow on the cover aligned with the dot on the housing after a bulb change. Refer to Technical Bulletin 86/05/04/NAS.

Figure 1



TIB 86/06/04/NAS	CIRCULATE: TO	Service Mgr X	Warranty X	Workshop X	Body Shop X	Parts X
---------------------	------------------	------------------	---------------	---------------	----------------	------------