

# Agilent AN 369-5

## Multi-frequency C-V Measurement of Semiconductors

### Application Note

#### Agilent E4980A and 4284A Precision LCR Meters

##### Introduction

Parameters such as the capacitance of the oxide layer ( $C_{ox}$ ) and the density of substrate impurities ( $N_{sub}$ ) that are required in the evaluation of the manufacturing process of MOS type semiconductors can be derived by using measured C-V characteristics. To make an accurate evaluation of these processes, precise C-V measurements are required. Such measurements entail the following difficulties.

##### Difficulties

1. There is no single instrument that can make C-V measurements from low to high frequencies.
2. It is difficult to compensate for the additional errors that occur when cable extensions or a probe are used.
3. The accuracy and reliability of the DC bias voltage are not sufficient to perform repeatable C-V measurements.

In the following discussion we will show how C-V measurements are performed with the E4980A and 4284A solving these problems.

#### Solutions Offered by the E4980A and 4284A

##### 1. Wide Frequency Range Measurements from 20 Hz to 2 MHz.

The program listing shown in the appendix was used to measure the C-V characteristics at 10 kHz, 100 kHz, and 1 MHz of the MOS device whose characteristics are shown in Figure 1.

Thus, the E4980A and the 4284A can single-handedly perform C-V measurements in both the low and high frequency ranges. This allows it to measure high-loss devices (semiconductors on large diameter wafers, etc.), which are difficult to measure at 1 MHz, at low frequencies (10 kHz, 100 kHz, etc.).




Figure 1. Multi-frequency C-V characteristics of a semiconductor



Agilent Technologies

## 2. Compensation Functions for Cable Extensions and Probers.

In order to test semiconductor devices on a wafer, an extension cable and a prober are required. (See Figure 2 and 3.) The extension cable and the prober cause additional errors that greatly influence the test value. The E4980A and 4284A's 2m/4m Cable Length Operation function with 16048D/E test leads, Option 006 for 4284A, minimizes additional errors caused by using 2m/4m extension cables. The E4980A and 4284A's open/short/load compensation functions minimize errors caused by a prober. This powerful compensation function ensures highly accurate C-V measurements even when a prober is used.




Figure 2. Cable extension and prober connection in four-terminal pair (4TP) configuration




Figure 3. Cable extension and prober connection in two-terminal pair (2TP) configuration

### 3. Highly Accurate Internal Bias

Insufficient accuracy and stability of the bias voltage applied to a device prevents accurate C-V measurements. The E4980A and 4284A ensure the application of a stable bias voltage with a maximum accuracy of 0.1% (Option 001). This minimizes measurement errors due to bias voltage errors.

**Table 1. E4980A Option 001 DC Bias Capability**

Range	Resolution	Accuracy*
±0 to 5 V	330 µV	± 0.1% + 2 mV
±5.001 to 10 V	1 mV	± 0.1% + 2 mV
±10.002 to 20 V	2 mV	± 0.1% + 2 mV
±20.005 to 40 V	5 mV	± 0.1% + 2 mV

**Table 2. 4284A Option 001 DC Bias Capability**

Range	Resolution	Accuracy*
±0.000 to 5 V	1 mV	± 0.1% + 1 mV
±4.002 to 8 V	2 mV	± 0.1% + 2 mV
±8.005 to 20 V	5 mV	± 0.1% + 5 mV
±20.01 to 40 V	10 mV	± 0.1% + 10 mV

\*This can only be used when the test signal level is < 2 Vrms

## Conclusion

The E4980A and 4284A feature a wide frequency range, powerful compensation functions, and highly accurate bias characteristics. This versatility of the meter guarantees highly accurate C-V measurements, and higher efficiency in the evaluation of semiconductor processes. Because the E4980A and 4284A can perform all of the low and high frequency C-V measurements singlehandedly, it will greatly contribute to the lowering of capital costs.

## Appendix 1. Agilent E4980A Sample Program List

```

10 ! ***** Agilent E4980A C-V MEASUREMENT SAMPLE PROGRAM *****
20 OPTION BASE 1
30 GCLEAR
40 PRINT CHR$(12)                                         ! CLEAR DISPLAY
50 DIM C(3,101),Cn(3,101),Vbias(101)
60 INTEGER H1,H2,H3,Tm
70 DIM D(101,4)
80 ASSIGN @Ad TO 717:FORMAT ON                           ! DEFINE I/O PATH
90 ASSIGN @Pat TO 717:FORMAT OFF                         ! DEFINE I/O PATH
100 REMOTE @Ad                                           ! SET E4980A TO REMOTE MODE
110 OUTPUT @Ad;"*Rst"                                    ! RESET E4980A
120 OUTPUT @Ad;"VOLT:LEV 0.02V"                          ! SET OSC LEVEL to 20mV
130 OUTPUT @Ad;"TRIG:SOUR BUS"                           ! GPIB TRIGGER MODE
140 OUTPUT @Ad;"FORM:DATA REAL"                          ! BINARY DATA TRANSFER
150 OUTPUT @Ad;"MEM:DIM DBUF,101"                        ! DEFINE BUFFER IN E4980A
160 OUTPUT @Ad;"MEM:FILL DBUF"                           ! ENABLE BUFFER TRANSFER
170 OUTPUT @Ad;"APER SHOR"                             ! SET INTEG TIME TO SHORT
180 GOSUB Corr
190 PRINT "CONNECT OUT AND PRESS CONTINUE"
200 PAUSE
210 PRINT CHR$(12)                                         ! CLEAR DISPLAY
220 Holdtime=10                                         ! HOLD TIME = 10sec
230 Delaytime=.1                                         ! DELAY TIME = 100msec
240 Vbias(1)=-5                                         ! START BIAS VOLTAGE
250 Vstep=.1                                            ! 100mV BIAS STEP
260 OUTPUT @Ad;"TRIG:DEL "&VALS(Delaytime)             ! SET DELAY TIME
270 OUTPUT @Ad;"OUTP:DCISOL:STAT ON"                   ! DCI ISOLATION ON
280 OUTPUT @Ad;"BIAS:STATE ON"                           ! BIAS ON
290 Freq$(1)=" 1MHz"
300 Freq$(2)=" 100KHz"
310 Freq$(3)=" 10KHz"
320 FOR I=1 TO 3
330     OUTPUT @Ad;"FREQ"&Freq$(I)                      ! FREQUENCY SETTING
340     OUTPUT @Ad;"BIAS:VOLT "&VALS(Vbias(1))          ! SET START BIAS VOLTAGE
350     PRINT TABXY(5,15);HOLD TIME 10SEC"
360     WAIT Holdtime                                    ! HOLD TIME
370     PRINT TABXY(5,15);MEASURING at "&Freq$(I)
380     FOR J=1 TO 101
390         OUTPUT @Ad;"trig"                           ! TRIGGER E4980A
400         IF J=101 THEN 430
410         Vbias(J+1)=Vbias(J)+Vstep                  ! CHANGE BIAS VOLTAGE
420         OUTPUT @Ad;"BIAS:VOLT "&VALS(Vbias(J+1)) ! SET BIAS VOLTAGE
430     NEXT J
440     OUTPUT @Ad;"MEM:READ? DBUF"                    ! READ BUFFER
450     ENTER @Pat;H1,H2,H3,D(*),Tm
460     FOR J=1 TO 101
470         C(I,J)=D(J,1)
480     NEXT J
490     IF MAX(C(*))=0 THEN Err                         ! CHECK IF MAX C VALUE IS 0
500     FOR J=1 TO 101
510         Cn(I,J)=C(I,J)/(MAX(C(*)))                ! NORMALIZE C VALUE
520     NEXT J
530     OUTPUT @Ad;"MEM:CLE DBUF;FILL DBUF"            ! CLEAR DATA IN BUFFER
540     PRINT CHR$(12)                                     ! CLEAR DISPLAY
550     NEXT I
560     OUTPUT @Ad;"BIAS:STATE OFF"                     ! BIAS OFF
570     GOSUB Plotting
580     GOTO Ending
590     !
600 ! ***** PLOT C-V *****
610 ! THE FOLLOWINGS ARE FOR PLOTTING THE MEASUREMENT DATA TO CRT.
620     !
630 Plotting: DEG                                       ! SET ANGLE UNIT TO DEGREE
640 GRAPHICS ON                                         ! PLOT NUMBERS AND LABELS
650 VIEWPORT 8,150,17,100
660 WINDOW 0,100,0,100
670 LDIR 0
680 LORG 2
690 CSIZE 4
700 MOVE 45,15
710 LABEL "BIAS (V)"
720 MOVE 8,23
730 LABEL "-5.0"
740 MOVE 49,23
750 LABEL "0"
760 MOVE 84,23
770 LABEL "5.0"
780 MOVE 5,98
    !

```

## Appendix 1. Agilent E4980A Sample Program List *continued...*

```

790 LABEL "1.0" !
800 MOVE 65,5 !
810 LABEL " 1MHz" !
820 MOVE 65,10 !
830 LABEL "100kHz" !
840 MOVE 65,15 !
850 LABEL " 10kHz" !
860 MOVE 78,5 !
870 DRAW 88,5 !
880 LINE TYPE 8 !
890 MOVE 78,10 !
900 DRAW 88,10 !
910 LINE TYPE 3 !
920 MOVE 78,15 !
930 DRAW 88,15 !
940 LINE TYPE 1 !
950 LDIR 90 !
960 MOVE 3,55 !
970 LABEL "Cap/Cox" !
980 LDIR 0 !
990 MOVE 5,28 !
1000 LABEL "0.0" !
1010 MOVE 5,98 !
1020 LABEL "1.0" ! END PLOT NUMBERS AND LABELS
1030 !
1040 VIEWPORT 25,125,40,95 ! DRAW AXES
1050 FRAME !
1060 WINDOW -5,5,0,1 !
1070 AXES 1,2,-5,0 ! END DRAW AXES
1080 !
1090 FOR I=1 TO 3 ! PLOT DATA
1100 MOVE Vbias(I),Cn(I,1) !
1110 FOR J=2 TO 101 !
1120 DRAW Vbias(J),Cn(I,J) !
1130 NEXT J !
1140 LINE TYPE 3 !
1150 IF I=1 THEN LINE TYPE 8 !
1160 NEXT I ! END PLOT DATA
1170 LINE TYPE 1
1180 RETURN !
1190 !
1200 Corr: ! ***** SUBROUTINE FOR CORRECTION *****
1210 ! THE FOLLOWINGS ARE FOR PERFORMING OPEN/SHORT COMPENSATION.
1220 !
1230 OUTPUT @Ad;"DISP:PAGE CSETUP" ! GO TO CORRECTION SETUP PAGE
1240 OUTPUT @Ad;"CORR:LENG 1;METH SING" ! CABLE LENGTH 1m, SINGLE COMPEN MODE
1250 OUTPUT @Ad;"CORR:SPOT1:FREQ 1MHz;STAT ON" ! SPOT FREQ 1 = 1MHz
1260 OUTPUT @Ad;"CORR:SPOT2:FREQ 100kHz;STAT ON" ! SPOT FREQ 2 = 100kHz
1270 OUTPUT @Ad;"CORR:SPOT3:FREQ 10kHz;STAT ON" ! SPOT FREQ 3 = 10kHz
1280 OUTPUT @Ad;"CORR:LOAD:STAT OFF" ! LOAD COMPEN OFF
1290 PRINT "OPEN COMPENSATION"
1300 PRINT TABXY(5,15);"PRESS CONTINUE"
1310 PAUSE
1320 PRINT TABXY(5,15);" "
1330 OUTPUT @Ad;"CORR:SPOT1:OPEN" ! PERFORM OPEN COMPEN AT SPOT FREQ 1
1340 OUTPUT @Ad;"CORR:SPOT2:OPEN" ! PERFORM OPEN COMPEN AT SPOT FREQ 2
1350 OUTPUT @Ad;"CORR:SPOT3:OPEN" ! PERFORM OPEN COMPEN AT SPOT FREQ 3
1360 OUTPUT @Ad;"OPC?" ! CONFIRM OPEN MEASUREMENT COMPLETED
1370 ENTER @Ad;AS
1380 OUTPUT @Ad;"CORR:OPEN:STAT ON" ! OPEN COMPEN ON
1390 PRINT CHR$(12) ! CLEAR DISPLAY
1400 PRINT "SHORT COMPENSATION"
1410 PRINT TABXY(5,15);"PRESS CONTINUE"
1420 PAUSE
1430 PRINT TABXY(5,15);" "
1440 OUTPUT @Ad;"CORR:SPOT1:SHOR" ! PERFORM SHORT COMPEN AT SPOT FREQ 1
1450 OUTPUT @Ad;"CORR:SPOT2:SHOR" ! PERFORM SHORT COMPEN AT SPOT FREQ 2
1460 OUTPUT @Ad;"CORR:SPOT3:SHOR" ! PERFORM SHORT COMPEN AT SPOT FREQ 3
1470 OUTPUT @Ad;"OPC?" ! CONFIRM SHORT MEASUREMENT COMPLETED
1480 ENTER @Ad;AS
1490 OUTPUT @Ad;"CORR:SHOR:STAT ON" ! SHORT COMPEN ON
1500 OUTPUT @Ad;"DISP:PAGE MEAS" ! GO TO MEASUREMENT PAGE
1510 PRINT CHR$(12) ! CLEAR DISPLAY
1520 RETURN
1530 !
1540 ! ****
1550 Err: PRINT "C-V MEASUREMENT FAILED."
1560 Ending: END

```

## Appendix 2. Agilent 4284A Sample program list

```

10 ! ***** Agilent 4284A C-V MEASUREMENT SAMPLE PROGRAM *****
20 OPTION BASE 1
30 GCLEAR
40 PRINT CHR$(12)
50 DIM C(3,101),Cn(3,101)Vbias(101) ! CLEAR DISPLAY
60 INTEGER H1,H2,H3,Tm
70 DIM D(101,4)
80 ASSIGN @Ad TO 717:FORMAT ON ! DEFINE I/O PATH
90 ASSIGN @Pat TO 717:FORMAT OFF ! DEFINE I/O PATH
100 REMOTE @Ad ! SET 4284A TO REMOTE MODE
110 OUTPUT @Ad;"Rst" ! RESET 4284A
120 OUTPUT @Ad;"VOLT:LEV 0.02V" ! SET OSC LEVEL TO 20mV
130 OUTPUT @Ad;"OUTP:HPOW ON" ! BIAS OPTION ON
140 OUTPUT @Ad;"TRIG:SOUR BUS" ! GPIB TRIGGER MODE
150 OUTPUT @Ad;"FORM:DATA REAL" ! BINARY DATA TRANSFER
160 OUTPUT @Ad;"MEM:DIM DBUF,101" ! DEFINE BUFFER IN 4284A
170 OUTPUT @Ad;"MEM:FILL DBUF" ! ENABLE BUFFER TRANSFER
180 OUTPUT @Ad;"APER SHOR" ! SET INTEG TIME TO SHORT
190 GOSUB Corr
200 PRINT "CONNECT OUT AND PRESS CONTINUE"
210 PAUSE
220 PRINT CHR$(12) ! CLEAR DISPLAY
230 Holdtime=10 ! HOLD TIME = 10sec
240 Delaytime=.1 ! DELAY TIME = 100msec
250 Vbias(1)=-5 ! START BIAS VOLTAGE
260 Vstep=.1 ! 100mV BIAS STEP
270 OUTPUT @Ad;"TRIG:DEL "&VAL$(Delaytime) ! SET DELAY TIME
280 OUTPUT @Ad;"OUTP:DC:ISOL ON" ! DC BIAS ISOLATION ON
290 OUTPUT @Ad;"BIAS:STATE ON" ! BIAS ON
300 Freq$(1)=" 1MHz"
310 Freq$(2)=" 100KHz"
320 Freq$(3)=" 10KHz"
330 FOR I=1 TO 3
340 OUTPUT @Ad;"FREQ"&Freq$(I) ! FREQUENCY SETTING
350 OUTPUT @Ad;"BIAS:VOLT "&VAL$(Vbias(1)) ! SET START BIAS VOLTAGE
360 PRINT TABXY(5,15);!"HOLD TIME 10SEC"
370 WAIT Holdtime ! HOLD TIME
380 PRINT TABXY(5,15);!"MEASURING at "&Freq$(I)
390 FOR J=1 TO 101
400 OUTPUT @Ad;"trig" ! TRIGGER 4284A
410 IF J=101 THEN 440
420 Vbias(J+1)=Vbias(J)+Vstep ! CHANGE BIAS VOLTAGE
430 OUTPUT @Ad;"BIAS:VOLT "&VAL$(Vbias(J+1)) ! SET BIAS VOLTAGE
440 NEXT J
450 OUTPUT @Ad;"MEM:READ? DBUF" ! READ BUFFER
460 ENTER @Pat;H1,H2,H3,D(*),Tm
470 FOR J=1 TO 101
480 C(I,J)=D(J,1)
490 NEXT J
500 IF MAX(C(*))=0 THEN Err ! CHECK IF MAX C VALUE IS 0
510 FOR J=1 TO 101
520 Cn(I,J)=C(I,J)/MAX(C(*)) ! NORMALIZE C VALUE
530 !PRINT Cn(I,J) ! PRINT NORMALIZED C VALUE
540 NEXT J
550 OUTPUT @Ad;"MEM:CLE DBUF;FILL DBUF" ! CLEAR DATA IN BUFFER
560 PRINT CHR$(12) ! CLEAR DISPLAY
570 NEXT I
580 OUTPUT @Ad;"BIAS:STATE OFF" ! BIAS OFF
590 GOSUB Plotting
600 GOTO Ending
610 !
620 ! ***** PLOT C-V *****
630 ! THE FOLLOWINGS ARE FOR PLOTTING THE MEASUREMENT DATA TO CRT.
640 !
650 Plotting: DEG ! SET ANGLE UNIT TO DEGREE
660 GRAPHICS ON
670 VIEWPORT 8,150,17,100 ! PLOT NUMBERS AND LABELS
680 WINDOW 0,100,0,100 !
690 LDIR 0 !
700 LORG 2 !
710 CSIZE 4 !
720 MOVE 45,15 !
730 LABEL "BIAS (V)" !
740 MOVE 8,23 !
750 LABEL "-5.0" !
760 MOVE 49,23 !
770 LABEL "0" !
780 MOVE 84,23 !
790 LABEL "5.0" !

```

## Appendix 2. Agilent 4284A Sample program list *continued...*

```

800 MOVE 5.98
810 LABEL "1.0"
820 MOVE 65.5
830 LABEL " 1MHz"
840 MOVE 65.10
850 LABEL "100kHz"
860 MOVE 65.15
870 LABEL " 10kHz"
880 MOVE 78.5
890 DRAW 88.5
900 LINE TYPE 8
910 MOVE 78.10
920 DRAW 88.10
930 LINE TYPE 3
940 MOVE 78.15
950 DRAW 88.15
960 LINE TYPE 1
970 LDIR 90
980 MOVE 3.55
990 LABEL "Cap/Cox"
1000 LDIR 0
1010 MOVE 5.28
1020 LABEL "0.0"
1030 MOVE 5.98
1040 LABEL "1.0" ! END PLOT NUMBERS AND LABELS
1050 !
1060 VIEWPORT 25.125.40.95 ! DRAW AXES
1070 FRAME !
1080 WINDOW -5.5,0.1 !
1090 AXES 1.2,-5.0 ! END DRAW AXES
1100 !
1110 FOR I=1 TO 3 ! PLOT DATA
1120 MOVE Vbias(I),Cn(I,I)
1130 FOR J=2 TO 101
1140 DRAW Vbias(J),Cn(I,J)
1150 NEXT J !
1160 LINE TYPE 3 !
1170 IF I=1 THEN LINE TYPE 8 !
1180 NEXT I ! END PLOT DATA
1190 LINE TYPE 1
1200 RETURN
1210 !
1220 Cor: ! ***** SUBROUTINE FOR CORRECTION *****
1230 ! THE FOLLOWINGS ARE FOR PERFORMING OPEN/SHORT COMPENSATION.
1240 !
1250 OUTPUT @Ad;"DISP:PAGE CSETUP" ! GO TO CORRECTION SETUP PAGE
1260 OUTPUT @Ad;"CORR:LENG 1:METH SING" ! CABLE LENGTH 1m, SINGLE COMPEN MODE
1270 OUTPUT @Ad;"CORR:SPOT1:FREQ 1MHz:STAT ON" ! SPOT FREQ 1 = 1MHz
1280 OUTPUT @Ad;"CORR:SPOT2:FREQ 100kHz:STAT ON" ! SPOT FREQ 2 = 100kHz
1290 OUTPUT @Ad;"CORR:SPOT3:FREQ 10kHz:STAT ON" ! SPOT FREQ 3 = 10kHz
1300 OUTPUT @Ad;"CORR:LOAD:STAT OFF" ! LOAD COMPEN OFF
1310 PRINT "OPEN COMPENSATION"
1320 PRINT TABXY(5,15); "PRESS CONTINUE"
1330 PAUSE
1340 PRINT TABXY(5,15); "
1350 OUTPUT @Ad;"CORR:SPOT1:OPEN" ! PERFORM OPEN COMPEN AT SPOT FREQ 1
1360 OUTPUT @Ad;"CORR:SPOT2:OPEN" ! PERFORM OPEN COMPEN AT SPOT FREQ 2
1370 OUTPUT @Ad;"CORR:SPOT3:OPEN" ! PERFORM OPEN COMPEN AT SPOT FREQ 3
1380 OUTPUT @Ad;"OPC?" ! CONFIRM OPEN MEASUREMENT COMPLETED
1390 ENTER @Ad;AS
1400 OUTPUT @Ad;"CORR:OPEN:STAT ON" ! OPEN COMPEN ON
1410 PRINT CHR$(12) ! CLEAR DISPLAY
1420 PRINT "SHORT COMPENSATION"
1430 PRINT TABXY(5,15); "PRESS CONTINUE"
1440 PAUSE
1450 PRINT TABXY(5,15); "
1460 OUTPUT @Ad;"CORR:SPOT1:SHOR" ! PERFORM SHORT COMPEN AT SPOT FREQ 1
1470 OUTPUT @Ad;"CORR:SPOT2:SHOR" ! PERFORM SHORT COMPEN AT SPOT FREQ 2
1480 OUTPUT @Ad;"CORR:SPOT3:SHOR" ! PERFORM SHORT COMPEN AT SPOT FREQ 3
1490 OUTPUT @Ad;"OPC?" ! CONFIRM SHORT MEASUREMENT COMPLETED
1500 ENTER @Ad;AS
1510 OUTPUT @Ad;"CORR:SHOR:STAT ON" ! SHORT COMPEN ON
1520 OUTPUT @Ad;"DISP:PAGE MEAS" ! GO TO MEASUREMENT PAGE
1530 PRINT CHR$(12) ! CLEAR DISPLAY
1540 RETURN
1550 !
1560 ! ****
1570 Err: PRINT "C-V MEASUREMENT FAILED."
1580 Ending: END

```

[www.agilent.com](http://www.agilent.com)



### Agilent Email Updates

[www.agilent.com/find/emailupdates](http://www.agilent.com/find/emailupdates)

Get the latest information on the products and applications you select.



### Agilent Direct

[www.agilent.com/find/agilentdirect](http://www.agilent.com/find/agilentdirect)

Quickly choose and use your test equipment solutions with confidence.



[www.agilent.com/find/open](http://www.agilent.com/find/open)

Agilent Open simplifies the process of connecting and programming test systems to help engineers design, validate and manufacture electronic products. Agilent offers open connectivity for a broad range of system-ready instruments, open industry software, PC-standard I/O and global support, which are combined to more easily integrate test system development.

## Remove all doubt

Our repair and calibration services will get your equipment back to you, performing like new, when promised. You will get full value out of your Agilent equipment throughout its lifetime. Your equipment will be serviced by Agilent-trained technicians using the latest factory calibration procedures, automated repair diagnostics and genuine parts. You will always have the utmost confidence in your measurements. For information regarding self maintenance of this product, please contact your Agilent office.

Agilent offers a wide range of additional expert test and measurement services for your equipment, including initial start-up assistance, onsite education and training, as well as design, system integration, and project management.

For more information on repair and calibration services, go to:

[www.agilent.com/find/removealldoubt](http://www.agilent.com/find/removealldoubt)

Product specifications and descriptions in this document subject to change without notice.

For more information on Agilent Technologies' products, applications or services, please contact your local Agilent office. The complete list is available at:

[www.agilent.com/find/contactus](http://www.agilent.com/find/contactus)

### Americas

Canada	(877) 894-4414
Latin America	305 269 7500
United States	(800) 829-4444

### Asia Pacific

Australia	1 800 629 485
China	800 810 0189
Hong Kong	800 938 693
India	1 800 112 929
Japan	0120 (421) 345
Korea	080 769 0800
Malaysia	1 800 888 848
Singapore	1 800 375 8100
Taiwan	0800 047 866
Thailand	1 800 226 008

### Europe & Middle East

Austria	01 36027 71571
Belgium	32 (0) 2 404 93 40
Denmark	45 70 13 15 15
Finland	358 (0) 10 855 2100
France	0825 010 700*
	*0.125 €/minute
Germany	07031 464 6333
Ireland	1890 924 204
Israel	972-3-9288-504/544
Italy	39 02 92 60 8484
Netherlands	31 (0) 20 547 2111
Spain	34 (91) 631 3300
Sweden	0200-88 22 55
Switzerland	0800 80 53 53
United Kingdom	44 (0) 118 9276201
Other European Countries:	<a href="http://www.agilent.com/find/contactus">www.agilent.com/find/contactus</a>

Revised: October 6, 2008

© Agilent Technologies, Inc. 2000,  
2006, 2008

Printed in USA, December 10, 2008  
5950-2953



Agilent Technologies