










Diagram of the XS2 connector showing pin connections for C11 through C16. Red arrows indicate the mapping from the connector pins to the component pins. The connector pins are labeled C16, C15, C14, C13, C12, C11, C17, and C10. The component pins are labeled R17, R13, R16, R12, R15, R11, R14, R10, and R24.

[illegible]

Примечание:
1. Вместо диода VD11 необходимо установить перемычку, либо низкоомный резистор, например МЛТ-0.125 100 Ом