Specifications:

RX Frequency	: 25 to 1500MHz
	: 50, 145, 435, 900 & 1200MHz.
Gain	: 5.12dBi
Max. Power	: 100 W
Impedance	: 50 ohm
V.S.W.R.	: Less than 1.5
	(at center of TX-frequency)
Length	: 1.4m
Weight	: 1.45 kg
Connector	: PL259 female type
Available Mast dia.	

Assembling Works:

Please refer to the right figs. and Parts List.

- Please mount Support Pipe onto your Pole, using Mount Bracket Assembly and U-Bolt. The distance from the low-end of the Mount Bracket to the low-end of the Support Pipe is to be 3cm approximately.
- Pass your coax. cable (w/PL-259 connector) through the Support Pipe and assemble to the Power Feeding Section. Please cover the connector joint part by the Self-Melting-Tape, prolonging twice as long, for complete water-proof.
- Then, mount the Power Feeding Section on the Support Pipe, and assemble it with Hex Bolt and Sp. Washer.
- Assemble 6 Disc Elements (with Caps.) to the Power Feeding Section and lock them with Nuts tightly.
- Please confirm again the tight-fastening of each screws, bolts and nuts.
- 6) Finally, assemble 6 Cone Elements (with Caps.) to the Power Feeding Section, and lock them with Nuts firmly.

The assembling works is finished completely.

How to adjust 50MHz TX-Frequency:

Pre-set center freq. is 51.00MHz.

Connect Transceiver, SWR meter and DS-150S.
STZ DS-150S

Transceiver	SWR Meter	Y
[2222] 0		

- Unfasten the Screw at 50MHz Top Element. Then, adjust length of the Top Element, watching SWR Meter. Lower freq.-longer, and higher-shorter.
- 3) Freq. change per each 1cm is 0.6MHz.
- When much higher freq. is proposed, you can cut off the low-end of the Top Element.

Please note that DS-150S comes with a 65 foot (20m) RG-589A/U coaxial cable with PL259 connectors attached.

Parts List:

No.	Parts Name	Qty
1)	Power Feeding Section	1pce
2)	50MHz Top Element	1"
3)	50MHz Loading Coil	1"
4)	50MHz Lower Element	1"
5)	Disc Element w/Nut	6"
6)	Disc Cap	6"
7)	Cone Element w/Nut	6**
8)	Cone Cap	6"
9)	Support Pipe	1"
10)	Fix Bolt & Sp. Washer	1"
11)	Mount Bracket, Nut & Sp.Wa	sher 1se
12)	U-Bolt, Nut & Sp. Washer	1"
13)	50MHz Ele. fix Screw	1pce
14)	Self-Melting Tape	1"
15)	Hex. Wrench	1"

COMET DS-150S

