		· · ·	Originator: DK
Products affected: DI BOX	······································		
Effective from serial number: 14 0211			
Reason for change:			
Introduction of MK 2.			
•			
Description of change:			
Description of change.			
New design.			
Circuit Diagram change? Y	New issue:	CD110 i	ssue 2
	New issue:	CD110 i	ssue 2
Parts List change? Y	New issue:		
Parts List change?YPCB Change?Y	New issue: New issue:	CD110 i PC110 i	
Parts List change?YPCB Change?YMetalwork change?Y	New issue:		
Parts List change?YPCB Change?YMetalwork change?Y	New issue: New issue:		
Parts List change?YPCB Change?YMetalwork change?YTest Specification change?Y	New issue: New issue: New issue:	PC110 i	
Parts List change?YPCB Change?YMetalwork change?YTest Specification change?Y	New issue: New issue: New issue:	PC110 i	
Parts List change?YPCB Change?YMetalwork change?YTest Specification change?Y	New issue: New issue: New issue:	PC110 i	
Parts List change? Y   PCB Change? Y   Metalwork change? Y	New issue: New issue: New issue:	PC110 i	