

PRS Five Position Rotary Wiring Diagram

Wiring Standard as of 1995

Rotary Positions

- 1) Position 10: Treble
- Position 10: Treble
 Position 9: Outside Coils
 Position 8: Series Single Coil
 Position 7: Parallel Single Coil
- 5) Position 6: Bass





PRS Guitars www.prsguitars.com 380 Log Canoe Circle Stevensville, MD 21666 USA