

Tel (781) 280-0300, Fax (781) 280-0499

## email: csupport@lexicon.com

## M300/L, M480L, Lares SERVICE BULLETIN

**SUBJECT:** Motorola has discontinued the MC68008 thru-hole part, Lexicon P/N 365-04594. A replacement adapter has been designed as its replacement.

**REFERENCE:** ECO 980417-00

**DISTRIBUTION:** International Pro-Product Distributor Service Centers, Customer Service, Repair

**CORRECTIVE ACTION:** When ordering a new replacement MC68008 for a repair, please use the following new Part #

Del:	365-04594	1	480L U34	300/L U25
Add:	024-12910	1	480L U34	300/L U25

Please contact LEXICON CUSTOMER SERVICE with any questions.