




Top of board (note that connector J3 is only used to help secure this board to the main board).



Bottom of board (copper pour layer is shown by dotted lines)





Top of board (copper pour layer is shown by dotted lines)

This is the first board and it has through-board holes and components, unlike the surface mount board shown on the previous page.

Carefully use a sharp blade to make sure there are no etching shorts in this region, where the traces are very close.

