



## 3-PHASE BRUSHLESS MOTOR DRIVER

—TOP VIEW—

**INPUT**

ANGLE ; INPUT/OUTPUT GAIN CONTROL  
 BR ; MOTOR CONTROL  
 (L : DRIVE/H : STOP)  
 FG +/- ; FG SIGNAL  
 FRC ; MOTOR FORWARD/REVERSE  
 CONTROL (L: FWD/H : REV)  
 STBY ; STANDBY (L : STANDBY)  
 U 1/2, V 1/2, W 1/2 ; CONTROL

**OUTPUT**

FG 1/2 ; FG AMP  
 U, V, W ; OUTPUTS

