## **Product Preview**

## Low-Voltage CMOS 16-Bit Latching Transceiver With 5V-Tolerant Inputs and Outputs (3-State, Non-Inverting)

The MC74LCX16543 is a high performance, non–inverting 16–bit latching transceiver operating from a 2.7 to 3.6V supply. The device is byte controlled. Each byte has separate control inputs which can be tied together for full 16–bit operation. High impedance TTL compatible inputs significantly reduce current loading to input drivers while TTL compatible outputs offer improved switching noise performance. A V<sub>I</sub> specification of 5.5V allows MC74LCX16543 inputs to be safely driven from 5V devices. The MC74LCX16543 is suitable for memory address driving and all TTL level bus oriented transceiver applications.

For data flow from A to B with the EAB LOW, the A-to-B Output Enable (OEAB) must be LOW in order to enable data to the B bus, as indicated in the Function Table. With EAB LOW, a LOW signal on the A-to-B Latch Enable (LEAB) input makes the A-to-B latches transparent; a subsequent LOW-to-HIGH transition of the LEAB signal will latch the A latches, and the outputs no longer change with the A inputs. With EAB and OEAB both LOW, the 3-State B output buffers are active and reflect the data present at the output of the A latches. Control of data flow from B to A is symetric to that above, but uses the EBA, LEBA, and OEBA inputs.

- Designed for 2.7 to 3.6V VCC Operation
- 5V Tolerant Interface Capability With 5V TTL Logic
- · Supports Live Insertion and Withdrawal
- I<sub>OFF</sub> Specification Guarantees High Impedance When V<sub>CC</sub> = 0V
- LVTTL Compatible
- LVCMOS Compatible
- · 24mA Balanced Output Sink and Source Capability
- Near Zero Static Supply Current in All Three Logic States (10μA) Substantially Reduces System Power Requirements
- Latchup Performance Exceeds 500mA
- ESD Performance: Human Body Model >2000V; Machine Model >200V

MC74LCX16543

LCX

LOW-VOLTAGE CMOS 16-BIT LATCHING TRANSCEIVER




**DT SUFFIX**PLASTIC TSSOP PACKAGE
CASE 1202–01

56 OEBA1 OEAB1 LEAB1 55 LEBA1 54 EBA1 EAB1 **GND** 53 GND 52 B0 Α0 51 B1 Α1 50 V<sub>CC</sub> VCC 49 B2 A2 48 B3 АЗ 47 B4 A4 110 GND 46 GND Α5 45 B5 A6 44 B6 43 B7 A7 14 42 B8 Α8 41 B9 Α9 40 B10 A10 39 GND GND 18 A11 38 B11 A12 20 37 B12 36 B13 A13 21 35 V<sub>CC</sub> VCC 34 B14 A14 23 33 B15 A15 24 GND 25 32 GND EAB2 31 EBA2 30 LEBA2 LEAB2 27 OEAB2 OEBA2

This document contains information on a product under development. Motorola reserves the right to change or discontinue this product without notice.



## **OUTLINE DIMENSIONS**



Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and

## How to reach us:

**USA/EUROPE**: Motorola Literature Distribution; P.O. Box 20912; Phoenix, Arizona 85036. 1–800–441–2447

MFAX: RMFAX0@email.sps.mot.com –TOUCHTONE (602) 244–6609 INTERNET: http://Design\_NET.com

JAPAN: Nippon Motorola Ltd.; Tatsumi–SPD–JLDC, Toshikatsu Otsuki, 6F Seibu–Butsuryu–Center, 3–14–2 Tatsumi Koto–Ku, Tokyo 135, Japan. 03–3521–8315

**HONG KONG**: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852–26629298



MC74LCX16543/D