


C-MOS 1CHIP STEPPING MOTOR CONTROL DRIVER

—SIDE VIEW—



INPUT

CK1, CK2 ; CLOCK
CW/CCW ; POSITIVE/NEGATIVE CHANGE
M1, M2 ; MODE SETTING
ENABLE ; ENABLE
REF IN ; OUTPUT REFERENCE SETTING
RESET ; RESET

OUTPUT

ø A ; ø A OUTPUT
ø A ; ø A OUTPUT
ø B ; ø B OUTPUT
ø B ; ø B OUTPUT
MO ; INITIAL DETECT
N FA ; Ach OUTPUT CURRENT DETECT
N FB ; Bch OUTPUT CURRENT DETECT
V MA, V MB ; OUTPUT POWER SUPPLY

OTHER

OSC ; CHOPPING FREQUENCY SETTING

