520MHz Dual Modulus Prescaler

The MC12025 is a dual modulus prescaler which divides by 64 and 65. Supply voltages of 4.75 to 5.25V may be connected to Pin 8.

- 520MHz Toggle Frequency
- Low-Power 9.5mA Typical
- Control Input Is Compatible WIth Standard CMOS and TTL
- Operating Supply Voltage of 5.0V ±0.25V
- Propagation Delay 30ns Typical

MAXIMUM RATINGS

Symbol	Characteristic	Range	Unit
V _{CC}	Power Supply Voltage, Pin 8	-0.5 to 7.0	Vdc
T _A	Operating Temperature Range	-40 to +85	°C
T _{stg}	Storage Temperature Range	-65 to +175	°C

ELECTRICAL CHARACTERISTICS ($V_{CC} = 4.75 \text{ to } 5.25 \text{V}$; $T_A = -40 \text{ to } +85 \text{°C}$)

Symbol	Characteristic	Min	Тур	Max	Unit
f _{max} f _{min}	Toggle Frequency (Sine Wave Input)	520		30	MHz
Icc	Supply Current		9.5	13.5	mA
VIH	Control Input HIGH (÷64)	2.0			V
V _{IH}	Control Input LOW (÷65)			0.8	V
V _{out}	Output Voltage	0.8	1.2		VPP
V _{in}	Input Voltage Sensitivity 30MHz 100–520MHz	400 100		800 800	mV _{PP}
tPLL	PLL Response Time1			t _{out} -42 2	ns

^{1.} tp_L = The period of time the PLL has from the rising output transition to the Modulus Control input edge transition to ensure proper modulus selection

2. t_{out} = Period of output waveform

PRESCALER BLOCK DIAGRAM VCC O Modulus 1 Control O Input Signal Input 0.001µF 6 Output 4 GND

MC12025

MECL PLL COMPONENTS

÷64/65
DUAL MODULUS
PRESCALER




P SUFFIX 8-LEAD PLASTIC PACKAGE CASE 626-05



D SUFFIX 8-LEAD PLASTIC SOIC PACKAGE CASE 751-05

Pinout: 8-Lead Plastic (Top View)






1/97

© Motorola, Inc. 1997 REV 3


OUTLINE DIMENSIONS



NOTES:

- DIMENSION L TO CENTER OF LEAD WHEN
 FORMED PARALLEL.
- PACKAGE CONTOUR OPTIONAL (ROUND OR SQUARE CORNERS).
- DIMENSIONING AND TOLERANCING PER ANSI Y14.5M, 1982.

	MILLIMETERS		INCHES	
DIM	MIN	MAX	MIN	MAX
Α	9.40	10.16	0.370	0.400
В	6.10	6.60	0.240	0.260
С	3.94	4.45	0.155	0.175
D	0.38	0.51	0.015	0.020
F	1.02	1.78	0.040	0.070
G	2.54 BSC		0.100 BSC	
Н	0.76	1.27	0.030	0.050
J	0.20	0.30	0.008	0.012
K	2.92	3.43	0.115	0.135
L	7.62 BSC		0.300 BSC	
М		10°		10°
N	0.76	1.01	0.030	0.040



NOTES:

- DIMENSIONING AND TOLERANCING PER ASME Y14.5M, 1994.
- 2. DIMENSIONS ARE IN MILLIMETERS.
- 3. DIMENSION D AND E DO NOT INCLUDE MOLD
- PROTRUSION.
 4. MAXIMUM MOLD PROTRUSION 0.15 PER SIDE.
- 5. DIMENSION B DOES NOT INCLUDE MOLD PROTRUSION, ALLOWABLE DAMBAR PROTRUSION SHALL BE 0.127 TOTAL IN EXCESS OF THE B DIMENSION AT MAXIMUM MATERIAL CONDITION.

	MILLIMETERS			
DIM	MIN	MAX		
Α	1.35	1.75		
A1	0.10	0.25		
В	0.35	0.49		
С	0.18	0.25		
D	4.80	5.00		
Е	3.80	4.00		
е	1.27	1.27 BSC		
Н	5.80	6.20		
h	0.25	0.50		
L	0.40	1.25		
θ	0°	7°		

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and was negligent regarding the design or manufacture of the part. Motorola and opportunity/Affirmative Action Employer.

How to reach us:

USA/EUROPE/Locations Not Listed: Motorola Literature Distribution; P.O. Box 5405; Denver, Colorado 80217. 303–675–2140 or 1–800–441–2447

Mfax™: RMFAX0@email.sps.mot.com – TOUCHTONE 602–244–6609 INTERNET: http://Design-NET.com

JAPAN: Nippon Motorola Ltd.; Tatsumi–SPD–JLDC, 6F Seibu–Butsuryu–Center, 3–14–2 Tatsumi Koto–Ku, Tokyo 135, Japan. 81–3–3521–8315

ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852–26629298



MC12025/D