


PWM SWITCHING MODE POWER SUPPLY CONTROLLER

—TOP VIEW—



INPUT

CS : SOFT START ON/OFF CONTROL

CT : GENERATOR TIMING CAPACITOR

IS(+) : SOURCE CURRENT INPUT AT OVER-CURRENT DETECTION

RT : GENERATOR TIMING RESISTOR

OUTPUT

FB : FEEDBACK

OUT : DRIVE

