ALLEN&HEATH




WARNING — HIGH VOLTAGES

Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.


Please contact your local Allen & Heath distributor for more details.


http://www.allen-heath.com/




A60114 ISSUE 4 MPS9 PCB AHB CMC SERIES

COMPONENT OVERLAY







A.C. input fuse 3AT. 1100 1.25 1AT Bomm 240v D.C. output -15v +15v

+48v

POWER SUPPLY RPS1

. **DC** ground not connected to **AC** earth. CAUTION high voltage hazard.

Disconnect AC supply before made in England by λHB POWER SUPPLY MODEL RPS AC input 50/60Hz.set for Fuse on front panel. removing covers. 8 +15v: DC outputs, total current serial no (**(n)**

> FUSE OUTPUT A + 15 V.DC
> OUTPUTB + 48 V.DC MAINS INPUT WARNING HIGH VOLTAGE INSIDE POWER SUPPLY SERIAL No. AHB LTD, LONDON, ENGLAND TYPE MPS 9 -V. AC ~ 50/60 H. 2.5 A MAX OJS A MAX

NOMINAL MAINS INPUT 220 V.AC 100 V.AC 240 V.AC 110 V.AC 96 - 106 V.AC 105 - 120 V.AC 210 - 230 V.AC 235 - 245 V.AC RANGE FUSE RATING - TYPE AT AT AT AT 20x5 14x4" 14x2" 20x5 mm III U.K. Japan Europe/Ireland TERRITORY America