TABLE OF CONTENTS

Air Filters & Manifolds
Battery & Rotating Electrics
Brakes - Front and Rear
Brake Pedals & Brake System19
Cooling System
Cylinder Block
Cylinder Head
Table of Contents & Design Modification History
Differential
Door Fittings
Engine Controls
Engine Electrics
Exhaust System & Manifolds10
Front Axle & Drive Shafts
Front Body Fittings
Fuel System
Glazing & Mirrors
Handbrake
Heating & Air Conditioning
Back Door & Rear Body Fittings
Injection Equipment9
Instruments & Switches
Interior Trim
Lighting
Miscellaneous Electrics
Oil Coolers
Propeller Shafts
Rear Axle & Drive Shafts
Rear Body Fittings
Suspension - Front14
Suspension - Rear15
Steering
Transmission - Automatic
Transmission - Transfer Box11
Transmission - Manual12
Wheels & Tires
Winers & Washers 24

Discovery I Parts Section & Design Modification History

Welcome to our ALL NEW parts section for Discovery I. Here you will find an expanded array of available hard parts for Discovery I vehicles including many helpful part explosion drawings designed to not only help you identify parts but easily understand parts assembly. You will also find below a thorough North American spec. design modification history that highlights all major vehicle changes for Disco I's in North America.

Discovery Series II Owners, Take Note: This parts section is inclusive of Discovery I parts only at this time. We are in development currently on an expanded parts section to include Discovery Series II parts. This new section will be available in future publications—stay tuned!

Vehicle Identification Information

Discovery I model years are easily identified by the two-letter suffix at the end of the vehicle's identification number (VIN.) The preceding three digits (either 128 or 124) also denote manual or automatic transmissions. With your VIN # and model year identified, you can easily identify your engine, gearbox and transfer case.

Design Modifications:

all Discovery I vehicles were:

Two-speed LT230 transfer box

• Dual air bags

Anti-loc brakes

ZF transmission

model year.

on	
IN	Model Year/Trans
ALJY128*RA	1994 manual
ALJY124*RA	1994 auto
ALJY128*SA	1995 manual
ALJY124*SA	1995 auto
ALJY128*TA	1996 manual
ALJY124*TA	1996 auto
ALJY128*VA	1997 manual
ALJY124*VA	1997 auto
ALJY128*WA	1998 manual
ALJY124*WA	1998 auto
ALJY124*XA	1999 auto

S۵

SA

SA

The North American spec. Discovery I went through a limited number of design modifications through its history. Introduced in North America in

• 3.9 liter engine (through 1995); 4.0 liter engine (1996 on)

• Five-speed R380 manual transmission or four-speed automatic

The following design change information is prepared by VIN suffix/model

year break and highlights the major vehicle design changes for the given

PRICES SUBJECT TO CHANGE.

Call for the Latest Pricing and Availability.

April of 1994, the vehicle was produced through 1999 and then replaced by Discovery Series II beginning with the mid-1999 model year. Standard on

Engine Identification:					
Displ.	Number	Comp Ratio	App. Years		
3.9	35D	9.35:1	1994 manual		
3.9	36D	9.35:1	1994 auto		
3.9	35D	9.35:1	1995 manual		
3.9	36D	9.35:1	1995 auto		
4.0	50D	9.35:1	1996 manual		
4.0	50D	9.35:1	1996-99 auto		

Gearbox & Transfer Case Identification:

Gearbox:(1994-99) R380 manual 53A00001 5 spd.; ZF 4-spd. (no prefix) auto. Transfer Case: (1994-99) LT230T 28D00001

VIN Suffix RA

(1994 model year)

Year of introduction.

VIN Suffix SA

(1995 model year)

• No significant changes

VIN Suffix TA

(1996 model year)

• Introduction of 4.0 liter engine with GEMS fuel injection system (Generic Engine Management System).

• Three trim levels available:

• SD: cloth interior with 5-speed transmission standard automatic optional.)

• SE and SE7: leather interior, twin sunroofs and eight way adjustable power seats standard. SE7 model had rear cab jump seats standard and a rear hydraulic step. The SE7 also included rear cab air conditioning.

Shop Online at www.AtlanticBritish.com

Table of Contents & Design Modification History

Ill. No. Part No. Description Qty. Rqd. CYLINDER BLOCK Remarks Legend -	Ill. No. Part No.
Engine (e) numbers: 35D = 3.9 liter, manual transmission, distributor ignition 36D = 3.9 liter, automatic transmission, distributor ignition 50D = 4.0 liter, electronic ignition MONEY-SAVING KITS NOTED IN RED TYPE	6 CAM BEAR #RTC5 #STC1 #SOUVEL #90602202
1 ENGINE, SHORT 4.0 Liter #9257A	9 9 5TUD #252513 19 PISTOR RIMES #STC1427 18 PISTOR #ERR26936 #ERR26936
2 ENGINE KIT #9257ABPK1	4 ANR2805
GASKET SET #STC2823	5 154545 6 RTC5918 STC1961G 7 ERR2640 8 90602202 9 252513 10 549911 11 ERR2958 12 90602025 13 RTC1718 RTC17181
1 9257 ENGINE, short, 3.9 liter, Genuine, new unit 1 (e) 35D, 36D engines 9257A ENGINE, short, 4.0 liter, Genuine, new unit 1 Replacement for 3.9 liter units R 1 1 2 9257ABPK1 ENGINE KIT, for 9257 and 9257A engines 1 1 Contains composite head gaskets set. 1 1	RTC17182 STC3724G STC4299G 14 602082 15 603600
conversion gasket set, 16 hydraulic lifters, all head bolts 3 STC2823 GASKET SET, conversion 1	15 602609 16 602061G

VISA



Ill. No.	Part No.	Description	Qty. Rqd.
110.			nqu.
17	RTC2117	BEARING SET, big end, standard	1
	RTC211710	(e) 35D, 36D engines BEARING SET, big end, + 0.010	1
	RTC211720	(e) 35D, 36D engines BEARING SET, big end, + 0.020 (e) 35D, 36D engines	1
	STC1426	BEARING SET, big end, standard, Genuine (e) 50D engines	1
18	STC909S	PISTON ASSEMBLY, standard (e) 35D, 36D engines	8
19	RTC6066S	PISTON RINGS, piston set, standard (e) 35D, 36D engines	8
	STC1427	PISTON RINGS, piston set, standard (e) 50D engines	8
20	ETC8686 ERR3720	CAMSHAFT (e) 35D, 36D engines	1 1
	ERR3720G	CAMSHAFT (e) 50D engines CAMSHAFT, Genuine	1
_		(e) 50D engines	
	C	amshaft, Chainwheel & Gear	
	21	○ ²³	L
	THRUST PLA #ERR5926 #ERR592		r
	22	a Du	
	CHAINWHEEI #610289 #ERR5086		
	25	CAMSHAF	т
	SPACER #ERC2839G	#ETC8686 #ERR3720 #ERR3720	5 1 <u>6</u>
	27 /ASHER		<u>×</u>
#EF	RC6552G	28	
		CHAIN #ERC7929	
	G	26 24	
		BOLT GEAR #602227 #614188	
F			
	1 6 1		
	11-3-3	TIMING CHAI	IN KII
	~	#9009A	
	O an		
	and a		
3	Burne	- A	
	VE !		
	19.0		
21	ERR5926	THRUST PLATE, camshaft, (e) 35D, 36D engines	1
22	610289	CHAINWHEEL, camshaft (e) 35D, 36D engines	1
	ERR5086	CHAINWHEEL, camshaft (e) 50D engines	1
23	ERC2838G	(e) 300 engines KEY, chainwheel, Genuine (e) 35D, 36D engines	
24	614188	(e) 35D, 36D engines GEAR, distributor drive (e) 35D, 36D engines	1

25 ERC2839G

26 602227

(e) 35D, 36D engines

(e) 35D, 36D engines

(e) 35D, 36D engines

BOLT, sprocket

SPACER, sprocket, Genuine

Cylinder Block

TO ORDER, CALL **1-800-533-2210** MasterCard. AMERICAN EXPRESS

1

1

Engine Components

Atlantic British has recently made a special purchase of remanufactured differentials, transmissions, transfer cases and short block engines. Now you can rebuild your entire drive train at a practical price. (Our 3.9 engine, for instance, costs less than an overhaul of your existing 3.9!) And of course, we offer all the gaskets, bearings, bolts, seals and valves you need to do the complete job. Call us, we'll be glad to outfit you with everything you need.

Filter

filter



and prevents dirty oil from draining back into your crankcase. An inexpensive way to help protect your engine. (Does not fit **Discovery Series II.)**

K&N Oil Filters - Long (1168KN) K&N Oil Filter - Short (3340KN)

GET THE COMPLETE K&N AIR AND OIL FILTER KIT INCLUDING AIR FILTER, AIR FILTER CLEANER AND SHORT OIL FILTER AT A VALUE PRICE!

Complete K&N Air & Oil Filter Kit Discovery I (9251K)



Ill. No.	Part No.	Description	Qty. Rqd.
38	ERR7280	GASKET, front cover	1
39	FCKIT	FITTING KIT, front cover,	1
		includes all bolts and washers	
		(e) 35D, 36D and 50D engines	
40	154545	PLUG, front cover	1
11	600001	(e) 35D, 36D engines	2
41	602201	DOWEL, locating water pump (e) 35D, 36D engines	2
42	NH605041	L NUT, front cover stud	1
		(e) 35D, 36D engines	
43	ERR3340X		1
	ERR3340		1
		OIL FILTER, short, Genuine	1 1
	3340KN		
	ERR1168X		1
	ERR1168		*NLA
	1168KN	OIL FILTER, long, K&N premium	1
			\frown

TECH TIP: Oil Pump & Front Engine Cover

The oil pump and front engine cover are one integrated unit, therefore you must replace the cover if you're going to replace the oil pump. When changing the front engine cover / oil pump, also consider replacing your water pump, hoses and polyvee 'serpentine' belt at the same time since they all must be removed and are probably worn. We offer complete water pump assemblies, hose kits and water pump hardware kits to make the job easier, see page 31 for more details.

*NLA = No Longer Available

PRICES SUBJECT TO CHANGE. Call for the Latest Pricing and Availability.

Shop Online at www.AtlanticBritish.com



MasterCard. DUCOVER AMERICAN

VISA

24 BOLT #60209 ROCKER SHAFT #6116591 19 ROCKER SHAFT ASSY Ì 1 23 LH ROCKER ARM 22 RH ROCKER ARM #602153 25 PUSH ROD #603378 21 PLUG 26 #154545 LIFTER #ERR49 #9011 **Rocker Cover** 31 FILLER CAP 34 #ERR52180 HOSE 30 FILLER CAP #ERR4258 #62503 32 VENTILATOR #ERC248 33 0 RING 29 SCREW #ERR7371 #564258 27 GASKET #602512 #LVC100260 28 SCREW #ERR7370

Rocker Shaft Assembly

Qty. Rgd.

2

14

6

2

2

4

8

8

8

16

16

1

2

2

*NLA

4

4

1

1

1

2/1

1

TO ORDER. CALL 1-800-533-2210

Ill. No. Part No.

Description

TECH TIP: Head Bolts & Composite Gaskets

Atlantic British recommends that head bolts never be re-used, as they stretch and will not re-torque properly, which can cause leaks. We also recommend replacing original gaskets with composite gaskets, as they seal better than standard original gaskets. We recommend only composite replacement gaskets - purchase the individual head gasket or get the gasket set for a complete cylinder head valve job. (see items 14 & 15).

*NLA = No Longer Available

Qty. Rgd.

20



No. Part No.	Description	Rqd.
Co	oler, Automatic Transmission	3
7 PIPE ASSY #UBP101030G	10 0 RING #ESR1594LG	SY 156
E		E KIT 8558
5 ESR1703 6 9355B	OIL COOLER ASSEMBLY, transmission	1
7 UBP101030	OIL COOLER PIPE KIT, transmission Automatic transmission; includes items 7, 8, 9 PIPE ASSEMBLY, transmission to cooler, Genuine	1
8 ESR3695	Automatic transmission PIPE ASSEMBLY, cooler to cooler, Genuine	1
9 UBP101020	Automatic transmission PIPE ASSEMBLY, cooler to transmission, Genuine	1
10 ESR1594L 11 AMR4948	Automatic transmission O RING, oil cooler pipes, Genuine SWITCH, oil temperature, Genuine Automatic transmission; from (e) 36D45567B on	6 1
~	Cooler, Engine	
12 PBP101150	PIPE ASSEMBLY, engine to radiator, upper Automatic transmission	1
13 PBP101160	PIPE ASSEMBLY, radiator to engine, lower Automatic transmission	1

Description

Part No.

Qty.

Ill. No. Part No.	Description	Qty. Rqd.		
NO.		кда.		
ENGINE	E CONTROLS			
REMARKS L				
	: i.d. (v) numbers: = 1996 model year			
MON	IEY-SAVING KITS NOTED IN RED TYP	E		
	1 ACTUATING LINE #ETC7875G	<		
11H1781 ANR5327 RTC4854	cruise control, Genuine 640GTRANSDUCER, vehicle speed sensing, Genuine 11. RUBBER PAD, accelerator pedal 7. ACCELERATOR CABLE From (v) TA700854 and TA531680 on CABLE KICKDOWN Automatic transmission 850G CASSETTE SPIRAL, cruise control, Genuine	1 1 1 1 1 1 1		
6	2 VEHICLE SPEED TRANSDUCER #YBE100540G			
	Hoses, Coolant			
Belts, Hoses, Coolant We always recommend that when you change one hose, you should change all related hoses. The same holds true for belts—check your belts for tiny cracks. If one belt has failed and the oth- ers have cracks, change all of your belts at the same time. Rule of thumb—if one has failed, the others are probably not far behind (This is why we sell these parts in complete money-saving kits; the job is much easier and less time-consuming this way.) Lastly, we recommend you change your engine coolant as well at recommended intervals, as it loses its protective temperature range over time and flushing helps remove radiator-clogging deposits. Note: Land Rover recommends a coolant change every 30K miles.				

PRICES SUBJECT TO CHANGE. Call for the Latest Pricing and Availability.

Shop Online at www.AtlanticBritish.com

4

O RING, oil cooler pipes

14 ESR1594L

Engine Controls

Oil Coolers &

Ill. No.	Part No.	Description	Qty. Rqd.
		•	
CI	DOLIN	G SYSTEM	
-	MARKS LE		
		e) numbers:	
		= 3.9 liter, manual transmis	ssion,
	dist	ibutor ignition	
	36D	= 3.9 liter, automatic transi	mission,
	dist	ibutor ignition	
	50D	= 4.0 liter, electronic ignition	on
	Vehicle i	.d. (v) numbers:	
	PA -	• 1994 model year; TA = 199	06 mv

MONEY-SAVING KITS NOTED IN RED TYPE





BUSH, radiator mounting

4

VISA

5 572312

No.	Part No.	Description	Qty. Rqd.
5	ESR1262G	ADAPTOR, oil cooler pipe, Genuine	2
7	9370D	HOSE KIT, cooling and heater (e) 35D, 36D through (v) RA098379; for system with water valve	1
	9370DA	HOSE KIT, cooling and heater (e) 35D, 36D from (v) RA098380 on;	1
	9370DB	for system without heater valve HOSE KIT, cooling and heater (e) 50D engines; not advanced evaporative loss models	1
	9370DC	HOSE KIT, cooling and heater	1
	HSCLK	(e) 50D engines; advanced evaporative loss models CLAMP KIT, radiator and heater hoses	*NLA
3	ESR1819	<u>Includes 16 clamps</u> HOSE, bottom	1
	PCH000070	Not advanced evaporative loss models G HOSE, bottom, Genuine	1
9	ESR3297	Advanced evaporative loss models HOSE, top From (v) RA098380 on	1
		10 HOSE	
		HOSE #ERC8598G 15 GASKET #ERR2429	
		HOSE #ERC8598G 15 GASKET #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429)
		HÖSE #ERC8598G 15 GASKET #ERR2429 #ERR2429 #ERR2429 #ERR2429)
		HÖSE #ERC8598G 16 GASKET #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429 #ERR2429	65K 5GK '65

	ERC8598G	HOSE, manifold jacket, Genuine	1
11	PCF101590		1
	PCF101590G	EXPANSION TANK, Genuine	1
12	NTC7161	CAP, expansion tank	1
13	ETC4765K	THERMOSTAT, 88C, with gasket	1
	ETC4765GK	THERMOSTAT, 88C, with gasket, Genuine	1
	ETC4765	THERMOSTAT 88C	1
	ETC4765G	THERMOSTAT, 88C, Genuine	1
14	ETC6135G	HOUSING, thermostat, Genuine	1
		(e) 35D, 36D engines	
15	ERR2429	GASKET, thermostat housing	1
	ERR2429G	GASKET, thermostat housing, Genuine	1
16	STC4378A/	WATER PUMP ASSEMBLY	1
	STC43780E		
	STC4378G	WATER PUMP ASSEMBLY, Genuine	1
	STC4378FK		*NLA
17	ERR4077	GASKET, water pump	1
	ERR4623	BELT, drive, polyvee	1
		(e) 35D, 36D engines	_
	ERR4623G		1
		BELT, drive, polyvee, Genuine (e) 35D, 36D engines	
	ERR5579	BELT, drive, polyvee (e) 50D engines	1
		(e) 50D engines	

Ill. No. Part No.

Description

Water Pump Assembly	
17 GASKET BERRA077	
19 TENSIONER #ERR3440 21 FAN #ERR3439 18 POLYVEE BELI #ERR4623	
22 COUPLING #ERR1443 20 PULLEY #POR101050	
ERR3440G TENSIONER, pulley, polyvee belt, Genuine */ 20 PQR101050 PULLEY, fan and water pump 21 ERR3439 FAN, radiator	1 VLA 1 1 1
TECH TIP: Polyvee 'Serpentine' Belt Change	
	-



Replacing your water pump polyvee or 'serpentine' belt is relatively simple (see item 18) - just use a wrench to pry back the belt tensioner. The hard part is remembering how to re-route the belt when you're done. This illustration should help. This is a good time to replace the belt tensioner (see item 19). A worn out tensioner can fail, destroying the new belt and leaving you stranded.

Cooling System

Qty. Rqd.

TO ORDER, CALL 1-800-533-2210 MasterCard. DUCOVER AMERICAN EXPRESS

*NLA = No Longer Available

Ill. No.	Part No.	Description
-------------	----------	-------------

FUEL SYSTEM

MONEY-SAVING KITS NOTED IN RED TYPE

Qty. Rgd. Ill. No





1	WFE500740G	FUEL TANK ASSEMBLY, Genuine	1
2	ESR3926K	Not advanced evaporative loss models KIT, fuel pump & sender unit Not advanced evaporative loss models;	1
	WFX101020K	includes pump, sealing ring, pipe nuts & olives KIT, fuel pump & sender unit, plus seal,	
3	ESR3926	Advanced evaporative loss models FUEL PUMP AND SENDER UNIT Not advanced evaporative loss models	1 1
	WFX101020	FUEL PUMP AND SENDER UNIT Advanced evaporative loss models	1
4	YMT100050G	HARNESS, fuel pump & sender unit, Genuine Advanced evaporative loss models	1
5	NTC5858G	LOCKING RING, fuel pump to tank, Genuine Not advanced evaporative loss models	1
	ESR3808G	LOCKING RING, fuel pump to tank, Genuine Advanced evaporative loss models	1
6	NTC5859G	SEAL, fuel pump to tank, Genuine Not advanced evaporative loss models	1
	WGQ500020G	SEAL, fuel pump to tank, Genuine Advanced evaporative loss models	1

Part No. Description



Ill. No. Part No. Description

Qty. Rgd.

AIR FILTERS

REMARKS LEGEND -Engine (e) numbers 35D = 3.9 liter, manual transmission, distributor ignition 36D = 3.9 liter, automatic transmission, distributor ignition 50D = 4.0 liter, electronic ignition Vehicle i.d. (v) numbers: RA = 1994 model year; VA = 1997 model year

MONEY-SAVING KITS NOTED IN RED TYPE



K & N Air Filter

The last air filter you'll ever have to buy! This high-flow air filter will help your engine breathe better so it can perform better. A special multi-cotton fabric acts as an



atomizer to eliminate the harsh effects of rain, dirt, grime, dust and smoke. After 30-40,000 miles you simply take it out, clean it, re-oil it and put it back—no replacement necessary!

Discovery I - K & N Filter (9251) K & N Service/Cleaner Kit (9244)

Shop Online at www.AtlanticBritish.com

Fuel System & Air Filters

Qty. Rgd.

Ill. No. Part No.	Description	Qty. Rqd.	[
INJECT	ion equipment		
REMARKS LI			8
	e) numbers:		9
	= 3.9 liter, manual transmission, ributor ignition		
36D	= 3.9 liter, automatic transmission,		:
	ributor ignition		:
	= 4.0 liter, electronic ignitioni.d. (v) numbers:		
	= 1994 model year		:
			1

MONEY-SAVING KITS NOTED IN RED TYPE



VISA

Ill. No.	Part No.	Description	Qty. Rqd.
	ERR4278	POTENTIOMETER, throttle position (e) 50D engines	1
7	ETC5599G	GÁSKET, potentiometer, Genuine	1
8	ERR5199	VALVE, idle air control (IACV) (e) 35D, 36D engines	1
9	ERR2926	GASKET, IACV housing (e) 35D, 36D engines	1
10	ERR4352	VALVE, idle air control (e) 500 engines	1
11	ERR4762	HOSE, flame trap to tee piece (e) 35D, 36D engines	1
12	ERR4765	TEE PIECE RESTRICTOR (e) 35D, 36D engines	1
13	ERR4763	HOSE, tee piece to plenum (e) 35D, 36D engines	1
14	ERR4764	HOSE, tee piece to manifold (e) 35D, 36D engines	1



 TECH TIP:

 Discovery I - PCV Tune Up

Pop the hood and look for oil leaks around your valve covers periodically. If you see any seepage (discern any discharge?), you probably have excessive carbon build-up in your pcv system that's causing undue pressure on your seals. It's a simple job to replace them and should be done sooner, rather than later.



24 Inlet 25 DOWEL BOIT #LYG101440 #LYG101450G Manifold - 20 GASKET 23 CLAMP #ERR7282 #LKJ500020 #ERR7306 21 22 SEAL ASKET KIT #9218 #602099 #ERR7283 #9218A 20 LKJ500020 GASKET, intake manifold 1 (e) 35D, 36D; (e) 50D through (v) VA558699 ERR7306 GASKET, intake manifold, valley, new style 1 (e) 50D from (v) VA558700 on 21 602099 SEAL, intake manifold gasket 2 (e) 35D, 36D; through (e) 50D36201A ERR7283 SEAL, intake manifold gasket 2 From (e) 50D36202A on 22 9218 GASKET KIT, intake manifold 1 (e) 35D, 36D; (e) 50D through (v) VA558699 9218A GASKET KIT, intake manifold 1 (e) 50D from (v) VA558700 on 23 ERR7282 CLAMP, seal 2 From (e) 50D36202A on 24 LYG101440 BOLT, flanged, intake manifold, short 1 Replaces earlier bolt and washer LYG101450G BOLT, flanged, intake manifold, long, Genuine 2 Replaces earlier bolt and washer DOWEL PIN, locating ram housing 25 602201 2 (e) 35D, 36D engines Not flanged type **TECH TIP:** Discovery 1 4.0 **Know Your Emissions System**

Qty. Rgd.

Ill. No.

Part No.

Description



If your Discovery I was built in October 1996 or later, it has a specific 'Evaporative Emissions Family' that will help you determine key fuel system replacement parts like oxygen sensors, fuel pump, fuel filler cap, fuel tank and filler pipe assembly, charcoal canister and more. To identify your 'Evap Family,' check your vehicle information label under the hood on the vertical face of the hood latch panel.

VLR1124AYPFE = Advanced Evaporative Loss System VLR1060AYPBC = Standard Evaporative Loss System Know your 'Evap Family' ID when calling to order fuel system parts!

TO ORDER, CALL 1-800-533-2210

Injection Equipment

ଛ

Air Filters

I. Part No. Description

Exhaust

Atlantic British should be your first and only source for exhaust parts for your Discovery. We have everything from clamps to catalytic converters to complete systems. They are easily shipped, easily installed and easily the best performing exhausts you can buy. Our complete packages come with everything you need pre-fitted and custom-manufactured for your Discovery—so it fits right the first time. And both of the stainless steel exhausts offered here are guaranteed to last the life of your Rover!

Borla Performance Stainless Steel Exhaust

Exhaust System

ance haust

The best exhaust system you can buy for your Rover, for several reasons. Aircraft-quality T-304 stainless steel construction is lighter and stronger than conventional steel and is used inside and out (not just a stainless coating). It's fully welded without crimping for unimpeded flow-through, with slip-fit connectors for an easy, secure fit. Maintenance-free sound absorbing materials maintains low dBs, protects against burnout and reduces shell temperature. and each Borla exhaust is precision-tuned to your vehicle to actually improve engine performance. GUARANTEED for 1 million miles—the best in the business! Legal in all 50 states. It all adds up to make this the last exhaust system you'll ever buy for your Rover!

Borla Stainless Steel Exhaust System - Discovery I (9927)

Falcon Performance Stainless Steel Exhaust

If you want a high-performance, stainless steel exhaust without the "high-performance" sound, the Falcon is your best choice. All Mandrel bends insure free

flow of exhaust gases, with no backups or gaseous odors, and the topquality stainless steel exterior is guaranteed for the life of your vehicle. The Falcon has it all: a quiet, high-performance, custom-fit stainless steel exhaust at a price less than the soft steel OEM system! Easily installed at your local garage.

Falcon Stainless Steel Exhaust - Discovery I (9933)

E)	(HAUS	Т	
REM	ARKS LEGEN	ID -	
١	•	(v) numbers: 95 model year; TA = 1996 model year	
	JA = 19		
	2	Exhaust System	
	SENSOR #ERR6729 #ERR1834 #AMR6244 7	1 DOWNPIPE #ESR3063 #ESR4106	
	STUD #ERR55		
	B GASKET #ETC4524		5582
		#ERR551K	\sim
	9 NUT ERR4245G	HEAT SHIELD	
"	LRR42450		
		5 EXHAUST SYSTEM #NTC7426K	Í
		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	13
			AR BRACKET ESR101G
		10 ULIVE #CRC4579L HCRC4579L HCRC4579L HCRC4579L HCRC4579L HCRC4579L HCC5634G HCC5634G HCC5634G HCC5634G HCC5634G	
1	ESR3063	DOWN PIPE, with catalytic converters ('Y' pipe) Through (v) SA135999; not advanced evap. loss models	1
	ESR4106	DOWN PIPE, with catalytic converters (" pipe) From (v) TA194200 and TA525034 through TA534103 and TA703236; not advanced evap. loss models	1
2	ERR6729	SENSOR, heated oxygen 1995 Model Year;	2
	ERR1834	not advanced evap. loss models SENSOR, heated oxygen From 1996 Model Year on;	4
	AMR6244	not advanced evap. loss models SENSOR, heated oxygen Advanced evaporative loss models	4
3	9933	EXHAUST SYSTEM, complete kit, Falcon stainless	1
4	9927	Includes centre and rear mufflers, plus clamps EXHAUST SYSTEM, 'Borla' High Performance, stainless	1
5	NTC7426K	Single muffler system EXHAUST SYSTEM, complete kit, standard	1
		Through (v) TA166329 and TA502742; includes centre and rear muffler, plus clamps	
6	ERR551K	STUD KIT, exhaust manifold Includes items 8 - 10 for one manifold	2
-	EXHBC	EXHAUST BAND CLAMP, for Stainless Steel Exhaust Systems	*NLA
7 8	ERR551 ETC4524	STUD, manifold to down pipe GASKET, manifold to down pipe	6 2
9 10	ERR4245G CRC4579L	NUT, manifold to down pipe, Genuine OLIVE, down pipe to exhaust system	6 1
11 12	ESR2421G NTC5634G	BRACKET, support, front, Genuine BRACKET, support, intermediate, Genuine	1 1
13 14	ESR101G NTC5582	BRACKET, support, rear, Genuine MOUNTING RUBBER	1 3
15	NTC7196	HEATSHIELD, exhaust	1

Qty. Rad. Ill. No.

Part No.

Description



Qty. Rad.

Need a new oxygen sensor? You need to know your vehicle's emissions system 'Evap Family' identification to determine the right sensor to order. See the 'Emissions Systems' tech tip on page 33 for more details and give us a call.

Shop Online at www.AtlanticBritish.com

Ill. Part No.	Description Q		III. Part No.	Description
No. Part No.	R	<u>īd.</u>	No. Fait No.	Description
REMARKS LE Engine ( 35D distr 36D distr 50D Vehicle i	ATIC TRANSMISSION GEND - e) numbers: = 3.9 liter, manual transmission, ributor ignition = 3.9 liter, automatic transmission, ributor ignition = 4.0 liter, electronic ignition i.d. (v) numbers: = 1996 model year		<ul> <li>9245</li> <li>9241</li> <li>9240</li> <li>RTC4268</li> <li>RTC4647G</li> <li>STC1060G</li> <li>RTC4276G</li> <li>0 RTC5818</li> <li>1 RTC5102</li> </ul>	MASTER KIT, ZF transmission Includes seals, gaskets and friction linings. Does not include filter OVERHAUL KIT, ZF transmission Includes gasket kit and friction linings GASKET KIT, ZF transmission FILTER KIT, ZF transmission Also includes items 6, 9 and 10 GASKET, sump PLUG, transmission drain, Genuine WASHER, drain plug sealing, Genuin O RING, oil screen, upper, Genuine O RING, oil screen, lower SEAL, oil pump shaft
	1 TRANSMISSION ASSY #FTC3099R #FTC4969R	r	Filter an 5 5 5 5 5 5 9240 6 GASKET #RTC4268	
7	2 MASTER KIT			
	#9246		B 12 DIFSTI #FTC44	CK SWIICH
	3 OVERHAUL KIT #9245		11 SEAL #RTC5102	14 COUPLING SHAFT #FTIC5090
R.			E	17 SELECTOR #RTC6683
1 FTC3099R	#9241 TRANSMISSION ASSY, ZF automatic, 1		2 FTC4474G 3 RTC4937G 4 FTC5090 5 FTC566 6 FRC7630G	DIPSTICK, Genuine Up to (e) 36052139C SWITCH, inhibitor and reverse lamps SHAFT, coupling From (v) TA178214 and TA509009 on CABLE ASSEMBLY, gearchange TRUNNION, cable, Genuine
FTC4969R	remanufactured, (e) 35D, 36D engines TRANSMISSION ASSY, 2F automatic, 1 remanufactured, (e) 50D engines \$757 refundable core charge included	1	7 RTC6683 BTR9926LNFC BTR9691LNFC	SELECTOR FILM, Genuine SHIFT ILLUMINATION UNIT, Genuine SHIFT ILLUMINATION TRIM RING, automatic

VISA

<ul> <li>9245</li> <li>9241</li> <li>9240</li> <li>RTC4268</li> <li>RTC4647G</li> <li>RTC4647G</li> <li>RTC4276G</li> <li>RTC4276G</li> <li>RTC5818</li> <li>RTC5102</li> </ul>	Does not include filter OVERHAUL KIT, ZF transmission Includes gasket kit and firction linings GASKET KIT, ZF transmission FLITER KIT, ZF transmission Also includes items 6, 9 and 10 GASKET, sump PLUG, transmission drain, Genuine WASHER, drain plug sealing, Genuine O RING, oil screen, upper, Genuine O RING, oil screen, lower SEAL, oil pump shaft	1 1 1 1 1 1 1 1 1
Filter ar	BRTC42	NG 7766 0 RING 0 RING #RTC5818 WASHER #STC1060G 7 DRAIN PLUG #RTC46476
12 DIPST #FTC44	SWITCH RTC4937G RTC4937G RTC4937G RTC4937G RTC4937G RTC4937G	15 CABLE ASSY #FTC566 16 TRUNION #FRC7630G
E	17     SELECTOR FI     #RTC6683	LM
<ol> <li>2 FTC4474G</li> <li>3 RTC4937G</li> <li>4 FTC5090</li> <li>5 FTC566</li> <li>6 FRC7630G</li> </ol>	DIPSTICK, Genuine Up to (e) 36D52139C SWITCH, inhibitor and reverse lamps, G SHAFT, coupling From (v) TA178214 and TA509009 on CABLE ASSEMBLY, gearchange	1 ienuine 1 1

Ill. No. Part No. Description

Qty. Rqd.

1

### **TRANSMISSION - TRANSFER BOX**



Qty. Rqd.

TO ORDER, CALL **1-800-533-2210** 

Ill. No.	Part No.	Description
-------------	----------	-------------

### MANUAL TRANSMISSION

#### **REMARKS LEGEND -**

Vehicle i.d. (v) numbers: RA = 1994 model year

#### **MONEY-SAVING KITS NOTED IN RED TYPE**



Ill. No Part No

**TECH TIP:** 

**Transmission - Maintenance** 

Each time you do maintenance on your

Discovery, be sure to do a quick check of

the transmission cooling lines for leakage.

These lines are made of steel and corrosion

can be a problem. Often it will be seen as

seepage on the line or red drops of Dexron

on your garage floor that isn't coming from

your power steering pump or steering box.

Qty. Rad.

Description

Ill. No. Part No. Description

Qty. Rgd.

8 REVERSE

SWITCH,

5-SPEED #AMR3918

R380

### **PROPELLER SHAFTS**

**REMARKS LEGEND -**Vehicle i.d. (v) numbers:

VA = 1997 model year



Qty. Rgd.



	2000 2000 2000	3 COUPLING #TVF100010G	
1	276483 TVC100010	GAITER, front propeller shaft UNIVERSAL JOINT, front and	1
2		rear propeller shafts	A/R
3	TVF100010G	RUBBER COUPLING, rear propeller shaft, Genuine	1
		Through (v) VA541627 and VA710668	-
4	9300	CONVERSION KIT, rear propeller shaft Eliminates rubber coupling by using	1
5	FRC8387	standard universal joint PROPELLER SHAFT ASSEMBLY, rear From (v) VA541628 and VA710669 on	1





Shop Online at www.AtlanticBritish.com

### **TECH TIP: Excessive Driveshaft Vibration**

If you're experiencing excessive vibration when accelerating or under load, the problem is often linked to the rubber coupling or 'donut' at the end of your driveshaft. Atlantic British has a replacement driveshaft and rear universal coupling that eliminates the noisy rubber coupling and the annoying vibration that comes with it. If that vibration goes away the instant you lay off the gas, this is your problem, and our Driveshaft Replacement Kit (Part #9300) is your solution.



VISA



😔 🚾 🎬 TO ORDER, CALL **1-800-533-2210** 



PRICES SUBJECT TO CHANGE. Call for the Latest Pricing and Availability.

13

Steering

Ill. Part No. Description Qty.
--------------------------------

	- Caller		1 SPRING & SHOCK KJ #9393 #9393HI #9374 #9392
1	9393	SPRING AND SHOCK KIT, car set, ARB	:
	9393HD 9374	SPRING AND SHOCK KIT, car set, ARB Heavy duty SPRING KIT, car set, ARB	
	9392	Medium duty SPRING KIT, car set, ARB Heavy duty	:
		2 BILSTEIN #9279B #9279D	
2	9279BK 9279D 9210	SHOCK KIT, car set, Bilstein Includes polybushes SHOCK KIT, car set, Bilstein SHOCK ABSORBER KIT, car set, standard	
3	9721	SUSPENSION BUSH KIT, car set, standard	
	9780	SUSPENSION BUSH KIT, car set, red polybushes	
		SUSPENSION BUSH KIT, car set,	



F	anhard Rod and Radius Arm	
5 REBUILD #BUT #BH114161 9 BUMP #575	PANHARD ROD #RBI100000 12 #NUT STOP	
4         RBI100000           5         9000           6         ANR3410           7         BH114161           8         NY114041L           9         575707           10         NTC6860           11         NRC4514           12         NY120041L           13         NRC6372K           14         NRC6372           15         572087           16         NH605041L	PANHARD ROD ASSEMBLY REBUILD KIT, panhard rod Includes items 6, 7, 8 BUSH, panhard rod BUT, panhard rod BUMP STOP, rubber BUSH, radius arm BUSH, radius arm to chassis NUT, radius arm to chassis SHOCK TOWER KIT Includes items 14, 15, 16 for two brackets SHOCK TOWER, front shock SECURING RING, mounting bracket NUT, securing ring	1 2 2 2 2 4 4 2 1 2 2 8
	17         TWIN SHOCK FITTING KIT         #BA2157	
17 BA2157	TWIN SHOCK FITTING KIT, front Includes brackets and fixings required	1
18 572315 NRC4306 9376 9380 9359 BA2104 BA2106 19 NTC6106 20 NRC9700 21 9271 9277 STC3703 9275 9383 9356 22 552818 9778	to fit twin front shock absobers COIL SPRING, front RH (blue stripe) COIL SPRING, front RH (blue & white stripes) COIL SPRING, front, medium duty, OME, each COIL SPRING, front, heavy duty, OME, each COIL SPRING, front, heavy-duty, pair SPRING, front, heavy-duty, pair RETAINER, coil spring SEAT, coil spring FRONT SHOCK KIT, pair, standard FRONT SHOCK KIT, pair, Bilstein SHOCK ASSEMBLY, front, standard, each SHOCK ASSEMBLY, front, standard, each SHOCK ASSEMBLY, front, blestein SHOCK ASSEMBLY, front, heavy duty, OME, each SHOCK ASSEMBLY, front, heavy duty, OME, each SHOCK BUSH KIT, front, axle set, red polybushes	1 1 1 1 1 2 2 1 1 2 2 2 8 8 1
9778B	SHOCK BUSH KIT, front, axle set, blue polybushes, Softer than red polybushes	1

Qty. Rqd. Ill. No.

Part No.

Description

Ill. No.

Part No.

Description

#### Springs, Shocks and Anti-Roll Bar 13 SHOCK TOWER KIT #NRC6372K 22 BUSH #552818 #9778 #9778B 16 15 NUT #NH605041L SECURING RING #572087 18 -SPRING 19 RETAINER #NTC6106 #572315 #NRC4306 #BA2104 #BA2106 20 SPRING SEAT #NRC9700 #9376 #9380 #9359 27 MOUNTING PIN #NTC8202 24 BUSH #NTC6828 21 Ø Ĩ. **26** BUSH #552819 SHOCK #9271 #9277 #STC3703 #9275 25 BALL JOINT #NTC1888 #9383 #9356 23 ANTI-ROLL BAR KIT #BA032 #9216 23 ANTI-ROLL BAR KIT **#BA032** 23 BA032 9216 ANTI-ROLL BAR KIT, front ANTI-ROLL BAR KIT HEAVY DUTY, rear 24 NTC6828 BUSH, anti-roll bar mounting, front 2 25 NTC1888 BALL JOINT ASSEMBLY, anti-roll bar 2 BUSH, ball joint 26 552819 4 27 NTC8202 MOUNTING PIN, ball joint (sway bar link bolt) 2 SUSPENSION CASTER KIT, ARB 28 9386 1 Corrects caster on lifted vehicles 28 CASTER KIT #9386

Qty. Rgd.

**TECH TIP:** Shock Absorber Towers - Maintenance

When it's time to change your front shock absorbers, you may find that the front shock towers have rusted, especially if you use your vehicle in salty conditions like we do in the Northeast. We offer the shock towers and their retaining rings as a time and money saving kit (see #13).

Shop Online at www.AtlanticBritish.com

Front & Rear Suspension



Ill. No. Part No.	Description	Qty. Rqd.
TOC-	12 SHOCK KIT #9272 #9278	
	16 TWIN SI FITTING #BA21!	KIT
<b>17</b> BUSH #NRC5591	3 CO Shock MOUNTING BR #NRC798	ACKET
18 BUSH #RNF100090L #9779 #9779B	14 NUT #FN1100 #92760 #92760 #9364 #UT04R	ท
12 9272 9278 13 STC3939 9276D 9384	REAR SHOCK KIT, pair, standard REAR SHOCK KIT, pair, Bilstein SHOCK ASSEMBLY, rear, standard SHOCK ASSEMBLY, rear, Bilstein SHOCK ASSEMBLY, rear, OME Gas filled	1 1 2 2 2
LTR04R 14 FN110041 15 NRC7981 16 BA2159	SHOCK ASSEMBLY, rear, ARB Long Travel Remote type NUT, flanged, rear shock mounting bracket MOUNTING BRACKET, rear shock TWIN SHOCK FITTING KIT, rear Includes brackets and fixings required to fit twin rear shock absorbers	2 6 2 1
17 NRC5593 18 RNF100090 9779 9779B	BUSH, upper, rear shock BUSH, lower, rear shock LBUSH, lower, rear shock SHOCK BUSH KIT, rear, axle set, red polybushes SHOCK BUSH KIT, rear, axle set, blue polybushes Softer than red polybushes	2 4 1 1
<b>(</b>	19       ANTI-R       BAR KI       #9216       #BA03	т
19 9216 BA034A	ANTI-ROLL BAR KIT, rear, heavy duty Includes bar and fittings ANTI-ROLL BAR KIT, rear, standard Includes bar and fittings	1 1

TO ORDER, CALL **1-800-533-2210** 

Ill. No. Part No. Description	Qty. Rqd.
Anti-Roll Bars	)
20 NTC7394 21 NTC1388 BUSH, anti-roll bar mounting, rear 22 552819 BUSH, ball joint 31 NTC82026 MOUNTING BOLT, ball joint, Genuine (sway bar link bolt) 24 AIR LIFT 1000 #9263	2 2 4 2 KIT
24 9263 AIR BAG SYSTEM, Air Lift 1000 Increases rear load capacity <b>TECH TIP:</b> Bilstein Shock Upgrades The rubber bushings earlier Bilstein shock were more than an quate for the rig of off-roading, In not always tou enough for the air wren of an over-zealous mechanic. Bilst has since buffed up their bushings with thi er, stronger rubber so even the burlin mechanic won't harm them. It is importa however, that you match the proper set Bilsteins to your Discovery. The Disco I has	cks de- ors but igh ich ein ck- est nt, of

ify your Discovery model when ordering.

**Rear Suspension** 

15



TA = 1996 model year Axle (a) numbers: 78L = front axle

#### **MONEY-SAVING KITS NOTED IN RED TYPE**



From (a) 78L53960A on

Part No.

Ill. No.

Qty. Rgd.

Description

Qty. Rgd.

**REPLACEMENT KIT.** 

20

SEAL #FTC1376

10 BUSH #FTC1374

23

BEARING

ETC 2065

31

BOLT #FTC3455G

2

2

2

2

2

2

*NLA

2

2

2

2

2

2

12

2

2

2

2

2

21

18

BEARING

17

GASKET #FTC3647

IVEL PIN KIT

14

**Swivel Housing and Stub Axle** 

29 BEARING #FTC861

22 SWIVEL PIN

28 SEAL #FTC5268

30

THRUST RING

seals require

SWIVEL PIN, lower

BUSH, ABS sensor

SWIVEL PIN, upper

STUB AXLE

Genuine

Genuine

OIL SEAL, ABS sensor

SWIVEL PIN KIT, upper

GASKET, lower swivel pin

BEARING, lower swivel pin

OIL SEAL, ABS sensor, Genuine

Includes bearing and thrust washer

GASKET, stub axle to swivel pin housing

SCREW, stub axle to swivel pin housing,

BEARING, upper swivel pin

PLATE, locking, Genuine

OIL SEAL, stub axle

BEARING, stub axle

THRUST RING

From Nov. 1996 on, approx.

25

GASKET

#FTC3648

15 DRAIN PLUG

#236070

**REPLACEMENT KIT. C.V. joint** 

Includes one C.V. joint plus all gaskets and

DRAIN PLUG, swivel pin housing

16

SWIVEL PIN

**#FRC2894** 

27

SCREW #SX110251G

₿.

24

STUB AXLE

26 LOCKING PLATE #FRC2310

14 9365

15 236070

18 606666

FTC1376

STC226 21

22 FTC2882

23 FTC2065

24 FTC3154

25 FTC3648

28 FTC5268

29 FTC861

30 FTC56

31 FTC3455G

SX110251G

FTC1376G

17 FTC3647

19 FTC1374

20

26 FRC2310

27

16 FRC2894

C.V Joint

#9365

#### Part No. Description

Ill. No.



Qty. Rgd.



BOLT, threadlocked, shock to housing,



joints, we strongly recommend you use our swivel housing grease which is much thicker and specifically formulated NOT to leak around your seals like the standard replacement oil often does. One bottle per side will keep your CV joints bathed in lubrication for the life of the joint.

VISA

Swivel Housing Grease - Bottle (STC3435) \$10.95 ea.

]	Part No.	Description

Qty. Price \$ Rgd. Per Piece

Ill. No.



### DIFFERENTIAL

REMARKS LEGEND -Vehicle i.d. (v) numbers: VA = 1997 model year Axle (a) numbers: 78L = front axle 47S = rear axle



1 DIFFERENTIAL ASSEMBLY #FTC5142 #FTC3723 #FTC5143G

If your original differential is worn, fear not. Our new replacement will get your Disco back to peak performance in no time.



works great under most conditions, but serious off-roading and articulation sometimes requires a lockable differential, so power is distributed to all wheels equally, and not shifted to "the wheels that slip" (if that wheel happens to be off the ground at the time!). The ARB Air Locker is an all-inclusive kit that can be efficiently installed by a qualified differential technician. Our guys swear by this system, and so will you the first time you use it! Differential; Rear Axle & Drive Shafts

TO ORDER, CALL **1-800-533-2210** 

### WHEELS & TIRES

### Wheels & Tires

Want an easy way to buy wheels and tires for your Discovery? Simply pick up the phone and order your genuine alloy or rugged steel wheels with your choice of tires that can be mounted and balanced prior to shipping. All you will have to do is put them on your Rover.



# TIRES - Discovery I

Highway Tires

a. Dunlop Radial Rover A/T -P235/70/16 Set of four

Standard OE Replacements Tires

b. Michelin Synchrone -P235/70/16 Set of four (9964)

Winter - Snow Tires

c. Nokian Hakkepelitta 1 -P235/70/R16 Set of four (96268)

#### Off-Road/ Mud Terrain Tires

- d. Goodyear MT/R P225/75/R16 Set of four (96288)
- e. Goodyear MT/R P235/85/R16 Raised Suspension Set of four (96298)
- f. NEW! Super Swamper 16" Tire 235/85/16 Set of four (9638A)



Shop Online at www.AtlanticBritish.com

Ill. No.	Part No.	Description	
BF	RAKE	<u>SYSTEMS</u>	
	-	<b>1</b> BRAKE FUILD	
		#2501 #2521	
	В	rake System	2 SERVO ASSE #STC128
МА	4 STER CYLINDE #STC1284	CAP AND SENSOR BRICSB31G	
RI	7 ESERVOIR KIT #STC2904	6 MASTER CYLINDER OVERHAUL KIT BSTC2903	
	<u> </u>		;]

1	2501 2521	BRAKE FLUID, Castrol, 12 fl.oz. BRAKE FLUID, Castrol, 1 Quart	A/R A/R
2	STC1286	SERVO ASSEMBLY, Girling	1
3	RTC5832	SERVO OVERHAUL KIT, Girling	1
4	STC1284	MASTER CYLINDER ASSEMBLY	1
5	RTC5831G	CAP AND SENSOR, master cylinder, Genuine	1
6	STC2903	OVERHAUL KIT, master cylinder	1
7	STC2904	RESERVOIR KIT, master cylinder	1
8	ANR1765	BRAKE HOSE, front	2
9	NTC3458	BRAKE HOSE, rear	2





**REAR HOSE** 

**#NTC3458** 

VISA

9

80000 8000 8000



Ill. No. Part No.	Description
----------------------	-------------

### **PEDALS & PADS**



**TECH TIP:** Auto Transmission Stuck in Park?

Can't shift out of park? Better check your brake lights. The problem may not be your transmission. It may only be your brake light switch. As a safety device, you must depress the brake before you shift out of park. When the switch fails, the solenoid in your transmission won't let you shift out of park, so you're stuck. If your brake lights don't come on when you depress the pedal, you need a switch. Call us and ask for item AMR2010G. If you must move the vehicle temporarily, a mechanic can jump the brake light switch connection, but the brake lights will not function and the vehicle should not be driven for any length of time.

Ill. No. Part No. Description

Qty. Rgd.

### HANDBRAKE



HANDBRAKE CABLE **#STC1528** 

Qty. Rad.



PRICES SUBJECT TO CHANGE. Call for the Latest Pricing and Availability.

MasterCard. DUCeVER AMERICAN TO ORDER, CALL **1-800-533-2210**  orake

### FRONT AND REAR BRAKES

#### **MONEY-SAVING KITS NOTED IN RED TYPE**

### **Brakes & Brake Pads**

Brake parts are a specialty at Atlantic British. We offer FOUR different pad choices—Land Rover Genuine pads, Standard "E"-rated pads (meeting or

exceeding OEM specs), Ferodo asbestos-free, anti-squeal pads and dustless, High-Performance Kevlar pads. Plus, of course, rotors and convenient, costeffective Brake Kits—all the seals, washers, pins and clips you need, all in convenient kit form and all specified 🗴 to your vehicle. No re-ordering forgotten parts. And no "brake mistakes" by ordering the wrong parts! See our full line of brake pads, rotors and complete kits to the right!

### **TECH TIP: Brake Fluid**



#2501

We recommend changing your brake fluid at least once every two years. Water is absorbed by the brake fluid and can find its way into every part of your braking system, from the calipers to the master cylinder, leaving rust, leaks and corrosion in its wake. That's why we also recommend changing your brake fluid with **Castrol's Low Moisture Absorption formu**la. Castrol LMA is specifically designed for the high rubber content of Rover seals and won't dissolve them the way synthet-

ics can, plus it won't absorb the water that can lead to corrosion down the road.

Castrol LMA Brake Fluid - 12 oz. (2501) Castrol LMA Brake Fluid - Quart (2521)

INO.	•	•	Kqu.
		KT #9 #9 #9 #9 #9 #9 #9 #9 #9 #9 #9 #9	AKE REBUILD 985 985F 985G 985HP 983 983F 984 984F Description Below
_			
	Brake	e Rotor	
	#STC1962 #STC1963 BRAKE PAD SET #STC9191L #STC3765G #STC9191F		4 #FRC7329 #FRC7329G #FRC7329HP
			FITTING KIT #STC8575
1	9985	BRAKE REBUILD KIT, front/rear brakes, s Includes 4 rotors, pads, hub seals, lock tabs and gaskets	standard 1
	9985F	BRAKE REBUILD KIT, front/rear brake with Ferodo pads Includes 4 rotors, pads, hub seals,	s, 1
	9985G	lock tabs and gaskets BRAKE REBUILD KIT, front/rear brakes, Includes 4 rotors, pads, hub seals, lock tabs and gaskets	Genuine 1
	9985HP	BRAKE REBUILD KIT, front/rear brake high performance Includes 4 drilled and slotted rotors,	1
	9983	Kevlar pads, hub seals, lock tabs and gasket BRAKE REBUILD KIT, front brakes only, Includes 2 rotors, pads, hub seals, lock tabs and gaskets	standard 1
	9983F	BRAKE REBUILD KIT, front brakes onl with Ferodo pads Includes 2 rotors, pads, hub seals,	у, 1
	9984	lock tabs and gaskets BRAKE REBUILD KIT, rear brakes only, s Includes 2 rotors, pads, hub seals, lock tabs and gaskets	tandard 1
	9984F	BRAKE REBUILD KIT, rear brakes only with Ferodo pads Includes 2 rotors, pads, hub seals, lock tabs and gaskets	, 1
2 <mark>3</mark>	STC1962 STC1963 AEU1547	CALIPER, front, RH CALIPER, front, LH SEAL KIT, caliper, per pair of pistons	1 1 4

Ill. No. Part No.

Description

Qty. Rad.

Ill. No.	Part No.	Description	Qty. Rqd.
4	FRC7329 FRC7329G FRC7329HI	ROTOR, front, standard ROTOR, front, standard, Genuine 2 ROTOR, front, high performance drilled	2 2
5	STC9191l STC3765G	and slotted FRONT BRAKE PADS, axle set, standard FRONT BRAKE PADS, axle set, standard,	2
	STC9191F STC9191HF		1 1
6	STC8575	high performance Kevlar FLITIING KIT, front brake pads, axle set Includes split pins and springs	1 1
	R	ear Caliper and Brake Rotor	
7	14 ABS BUSH #FTC1374 13 ABS RING #FTC1379 9 REAR ROTIOR #FTC13816 #FTC13816 #FTC13816	10 BRAKE FAD SET #STC91886 #STC9188F #STC9188HP #STC9188HP #STC9188HP	11 TTING KIT STC6574
, 8 9	STC1265 AEU1547 FTC1381 FTC1381G FTC1381HF	CALIPER, rear, LH SEAL KIT, caliper, per pair of pistons ROTOR, rear, standard ROTOR, rear, standard, Genuine	1 2 2 2
10	STC8569 STC9188G	REAR BRAKE PADS, axle set, standard REAR BRAKE PADS, axle set, standard, Genuine	* <b>NLA</b> 1
	STC2953G	Alternative to STC29536 REAR BRAKE PADS, axle set, standard, Genuine Alternative to STC85696	1
	STC9188F STC9188HF	REAR BRAKE PADS, axle set, Ferodo	1 1
<mark>11</mark> 12	STC8574 591628 591629	FITTING KIT, rear brake pads, axle set SHIM, rear brake pad, LH outer or RH inner SHIM, rear brake pad, RH outer or LH inner	1 2 2
13 14	FTC1379 FTC1374	RING, ABS sensor BUSH, ABS sensor	2 2

PRICES SUBJECT TO CHANGE.

Call for the Latest Pricing and Availability.

### Shop Online at www.AtlanticBritish.com

20

Front & Rear Brakes

#### Qty. Rgd.

**TECH TIP:** Ground-Based **Electrical Problems** 

#### **Troubleshooting Vehicle:** Discovery 1994-1996

Poor grounds can cause numerous problems on a 1994 - 1996 Discovery. The following are main ground locations and the components they effect. To clean the contact surface, remove the fastener and use a wire brush to clean the post, connector and nut as needed. Spraying on a little contact cleaner may help, too. If the contact point is painted, a star washer can also be added to improve the connection.

**Check these ground locations:** 

- **1.** Right inner fender, behind the battery. Battery and EMC on 1994 & 1995 models.
- 2. Below the battery, inside the right frame rail. Battery ground.
- 3. Right of the left cylinder head. ECU. AC compressor clutch on 1994 & 1995 models.
- 4. Right frame rail, inside wheel well. Starter.
- 5. Left footwell, behind trim panel. ECM, key switch, radio, OBDII data link.
- 6. Right footwell, behind trim panel. Starter solenoid relay, park-neutral position switch, alarm, data link connector.
- 7. Left side of luggage compartment, behind access panel for taillights, above light assembly. Fuel pump, fuel level sensor.

VISA

Part No. Description



you own and protect your lawn tractor,

snowmobile, boat, etc. from corrosion, too!

ALTERNATOR, 100 amp, new

ALTERNATOR, 100 amp, new

BELT, drive, polyvee, Genuine (e) 35D, 36D engines

ALTERNATOR FIXING KIT

(e) 35D, 36D, 50D engines

BELT, drive, polyvee

(e) 35D, 36D engines

BELT, drive, polyvee

STARTER FIXING KIT

(e) 50D engines NAD101490 STARTER MOTOR ASSEMBLY

(e) 35D, 36D engines

(e) 50D engines

Battery Mat (9108)

7 AMR3107A

AMR4247

**D1ALTFK** 

ERR4623

ERR4623G

ERR5579

STARTEK

Alternator

B -

#ERR4623

#ERR4623G #FRR5579

8

9

### **BATTERY AND ROTATING ELECTRICS**

#### **REMARKS LEGEND -**

Qty. Rad.

**6** BATTERY MAT

#9108

1

1

*NLA

1

1

1

1

ALTERNATOR AMR3107A

#AMR4247

Q STARTER MOTOR INAD101490

ANT NOT

- Engine (e) numbers: 35D = 3.9 liter, manual transmission,
  - distributor ignition
  - 36D = 3.9 liter, automatic transmission,
  - distributor ignition
- 50D = 4.0 liter, electronic ignition

### **MONEY-SAVING KITS NOTED IN RED TYPE**



The revolutionary Optima Battery features patented Spiralcell technology that lasts up to 3 times longer than conventional flat-plate batteries! The Optima's totally-sealed design will not leak even if it's cracked open. And, it's much more resistant to jarring and vibration common to off-road driving (a primary killer of conventional liquid-filled batteries). Choose the regular cell with 800 Cold Cranking Amps, or the deep cycle with 750 C.C.A. for winching or other situations that require occasional recharging.

Optima Spiralcell Battery – Red – Regular Cycle (9603) Optima Spiralcell Battery – Yellow – Deep Cycle (9602)

```
*NLA = No Longer Available
```

Battery જ **Rotating Electrics** 

asterCard. TO ORDER. CALL **1-800-533-2210** 

Ill. No.	Part No.	Description
-------------	----------	-------------

### **ENGINE ELECTRICS**

#### **REMARKS LEGEND -**

Engine (e) numbers: 35D = 3.9 liter, manual transmission, distributor ignition 36D = 3.9 liter, automatic transmission, distributor ignition 50D = 4.0 liter, electronic ignition Vehicle i.d. (v) numbers: SA = 1995 model year

#### MONEY-SAVING KITS NOTED IN RED TYPE

Qty. Rgd. Ill. No

Part No.

Description





13 COIL LEAD **#STC9124 #STC9124G** SPARK PLUG, Bosch Platinum 8 ETC6437P Alternative to ERR3799 12 RTC6551D LEAD SET, high tension LEAD SET, high tension, Genuine RTC6551GD (e) 350, 360 engines LEAD SET, high tension, Genuine 9206 (e) 50D engines 9206A LEAD SET, high tension 13 STC9124 COIL LEAD, with cover 1 (e) 35D, 36D engines STC9124G COIL LEAD, with cover, Genuine 1 (e) 35D, 36D engines Distributor 16 14 DISTRIBUTOR CAP 20 VACUUM ADVANCE #STC8368 #ERR5209 #ERR4738 #RTC3197 #STC1186G #STC83 #STC83681 17 19 ROTOR ARM AMPLIFIER #STC1857A #STC1184 #STC18571 18 15 BASE PLATE #RTC5090 #STC2898 21 SERVICE KIT #RTC5971G O RING #6034466 14 ERR5209 DISTRIBUTOR ASSEMBLY 1 From (e) 35D09450B and 36D28464B; as shown no module on distributor. Not (e) 50D ERR4738 DISTRIBUTOR ASSEMBLY, Genuine 1 May be used to replace ERR4755 with module on distributor 15 RTC5971G SERVICE KIT, distributor, Genuine 1 Includes all screws, seals and retainers for distributor 16 STC8368 CAP, distributor 1 May be used to replace RTC3197 RTC3197 CAP, distributor 1 Original fitment type for ERR4755 and ERR5209G STC8368G CAP, distributor, Genuine 1 May be used to replace RTC3197 STC8368L CAP, distributor, Lucas 1 May be used to replace RTC3197 17 STC1857A ROTOR ARM 1

Qty. Rgd.

1

1

1

1

1

1

1

1

1

Ill. No. Part No.

Description

Coils 24 COIL PACK 22 COIL #FRR62696 #RTC5628 #PRC6574 23 LINK LEAD #PRC6144 22 RTC5628 COIL, ignition, Lucas 1 (e) 35D, 36D engines PRC6574 COIL, ignition, Bosch (e) 35D, 36D engines 23 PRC6144 LÍNK LEAD, ignition coil, Genuine 1 (e) 35D, 36D engines 24 ERR6269G COIL PACK, ignition, Genuine 1 (e) 50D engines 25 TUNE UP KIT **#9199G #9199E** 26 **EMERGENCY KIT** #9226 25 9199G TUNE UP KIT, premium Includes Bosch Platinum plugs and Lucas cap and rotor arm 9199E TUNE UP KIT, standard EMERGENCY KIT, breakdown 26 9226

Through 1995 model year

Qty. Rgd.

Shop Online at www.AtlanticBritish.com

ROTOR ARM, Genuine

BASE PLATE AND PICK UP

BASE PLATE AND PICK UP

Through (e) 35D09449B and 36D28463B

From (e) 35D09450B and 36D28464B on

O RING, distributor shaft, Genuine

Fit with link lead STC1212G if replacing 2 pin module

LINK LEAD, module to harness, 3 pin type,

RELOCATION KIT, amplifier module, Genuine From (e) 35D09450B and 36D28464B on

VACUUM ADVANCE UNIT, 3 pin type, Genuine

MODÙLE, amplifier, 3 pin type

ROTOR ARM, Lucas

Genuine

STC1857G

STC1857L

STC2898

STC1212G

STC1856G

20 STC1186G

21 603446G

18 RTC5090

19 STC1184





TURN INDICATOR LAMP, front LH	1
TURN INDICATOR LAMP, front RH	1
BULB HOLDER, turn indicator lamp	2
BULB, turn indicator	2
	TURN INDICATOR LAMP, front RH BULB HOLDER, turn indicator lamp





🚾 💮 📨 TO ORDER, CALL **1-800-533-2210** 

Ill. No.	Part No.	Description	Qty. Rqd.
23 24 25	1868 RTC3633 AMR1292G AMR2575 AMR1293G AMR2576 AFU4481G STC966G	BULB, high level stop lamp BULB, number plate SIDE MARKER LAMP, RH front, amber, Genuine SIDE MARKER LAMP, RH front, amber, Genuine SIDE MARKER LAMP, RH rear, red, Genuine BULB, side marker lamp, Genuine BULB, side marker lamp, Genuine BULB HOLDER AND HARNESS, side marker lamp, Genuine	1 2 1 1 1 4 4
	26	Driving and Fog Lamps	



ghting

Ill. No. Part No. Description



	Rear Wiper and Motor		
	10 WIPER BLADE HAMR1806SLL #AMR1806SW	REAR WIPER MOTOR BDLBIOIGAO	<b>X</b>
8	AMR1805	WIPER BLADE, windshield, standard Through 1999 model year	2
	AMR1805SIL	WIPER BLADE, windshield, silicone Through 1999 model year	2
	AMR1805W	WIPER BLADE, windshield, winter grade Through 1999 model year	2
9	DLB101640	WIPER MOTOR ASSEMBLY, rear screen	1 * <b>NLA</b>
10	WWH AMR1806	HOSE, Windshield Washer, 5 ft. WIPER BLADE, rear screen, standard	^ <i>NLA</i> 1
	AMR1806SIL AMR1806W	WIPER BLADE, rear screen, silicone WIPER BLADE, rear screen, winter grade	1 1
TECH TIP:     Image: Constraint of the second			

Description

It's not a bad idea to install winter wiper blades before the snow and ice set in. Winter wipers are easily recognized by their protective rubber cover over the wiper to prevent ice build up and keep it flexible (and your windshield clear!). We also recommend you check your wiper bolts when changing your wipers. Just lift the plastic cap on the base of the wiper arm and you'll find a 13mm nut. With the wipers off, adjust the wiper arm to its correct stationary position and tighten, if necessary.

WINTER WIPER BLADES

#AMR1805V



Qty. Rgd.

### Description



11	AMR5083G	RESERVOIR, windshield washer, Genuine	1
12	PRC6857G	From (v) 1996 model year on VALVE, non-return, windshield, Genuine	1
13	AMR6676	For 5mm dia tubing VALVE, non-return, rear screen For 4mm dia tubing	1
14	PRC7304	JET ASSEMBLY, windshield washer	2
	PRC6496	JET ASSEMBLY, rear screen washer From (v) TA169766 and TA503644 on	1
16	AMR1890	JET ASSEMBLY, headlamp washer	2
17	DCP6656	T-PIECE AND VALVE, headlamp washer	1
18	AMR3271	WASHER PUMP, front washer	*NLA
	DMC10023	WASHER PUMP, rear washer	*NLA
	AMR3661	WASHER PUMP, headlamp washer	*NLA
	AFU4506	GROMMET	*NLA
		for pumps AMR3271, DMC10023 and AMR3661	





If you're constantly running out of headlamp washer fluid, the problem is usually a leaky check valve, which allows the fluid to gravity-feed out of the jets beneath your headlamps. The T-piece check valve (see item 17) is a simple replacement and located under the bumper on the passenger side.

*NLA = No Longer Available

Qty. Rqd.





AMR2497G

PRC5254

PRC5255

PRC8096

PRC8095

PRC6029G

PRC6030G

PRC6031G

PRC6032G

19

20

21

22

23

Ill. No. Part No	D. Description	Qty. Rqd.
24 AWR22 AWR22		1 1
Su L	Inroof and Courtesy Lamp Switcher	CH A
25 AMR24 26 AMR36 27 PRC854	52G SWITCH, sunroof, rear, Genuine	1 1 5
	H TIP: covery Clock Replacement	<b>X</b>
replace removi as foll 1. Re a)	your clock unit has failed, it is ed with part #STC1800G (see 4), how ng the old unit requires some specific ows: emove drinks tray Remove ashtray by pushing spring clip down emove auxiliary switch panel, it snaps out.	wever, steps
	Remove six screws holding tray. Three in ea	
cl (tv be	bs hold the ock in place here wo on top, two clow-not shown)	
2. Ro fo	emove clock by releasing our tabs that hold the clock in place	
as	To release the tabs, insert a thin strip of meta a feeler gauge at four places indicated in pic ou will need to do all four at the same time	ture.
b)	Slide clock out and disconnect electrical plug	S.
c)	Install new unit by connecting electrical plugs	and

1

1

1

1

1

1

1

1

d) Install drinks tray, ashtray and switch panel.

PRICES SUBJECT TO CHANGE. Call for the Latest Pricing and Availability.

VISA

SWITCH, isolator, window lift, Genuine

SWITCH, window lift, rear door, RH

SWITCH, window lift, rear door, LH

SWITCH ASSY, seat, non-memory, LH

SWITCH ASSY, seat, non-memory, RH

KNOB, switch, squab adjust, LH, Genuine

KNOB, switch, squab adjust, RH, Genuine

KNOB, switch, cushion adjust, LH, Genuine

KNOB, switch, cushion adjust, RH, Genuine

Instruments and

Switches



### MISCELLANEOUS ELECTRICS

**REMARKS LEGEND -**

Vehicle i.d. (v) numbers:

SA = 1995 model year; TA = 1996 model year

IA = 1996 model year





Ill. No. Part No.	Description
----------------------	-------------

Qty. Rgd.

> 8 TRAILER WIRING KIT #9439A **Relays, Sensors and Horn** 12 ABS SENSOR AND HARNESS 10 YELLOW RELAY #STC1749 #STC1750 11 GREEN RELAY 9 FUEL PUMP RELAY #YWB10032 #AFU29130E 15 16 SUNROOF MOTOR HORN #YEB500040G #AMR3467G FG01002306 MAINTENANCE REMINDER 13 WINDOW CONTROL UNIT #PRC7038G #AMR5551 #AMR12820 12 STC1749 SENSOR AND HARNESS ASSY, ABS, front 2 SENSOR AND HARNESS ASSY, ABS, rear STC1750 1 13 AMR1282G ELECTRONIC CONTROL UNIT, window lift, Genuine 1 14 PRC7038G RELAY, emissions maintenance reminder, Genuine 1 Through (v) TA194199 and TA525033 AMR5551 RELAY, emissions maintenance reminder 1 From (v) TA194200 and TA525034 on 15 YEB500040G HORN, high note, Genuine 1 AMR3467G HORN, low note, Genuine 16 EG0100230G MOTOR ASSEMBLY, sunroof, front and rear, 2 Genuine Antenna 17 MANUAL ANTENNA #AMR3461 18 LINK LEAD #AMR3462G One ANTENNA, audio system, manual 17 AMR3461 1 Through (v) TA534103 and TA703236 AMR3461G ANTENNA, audio system, manual, Genuine *NLA Through (v) TA534103 and TA703236 18 AMR3462G LINK LEAD, manual antenna, Genuine 1 Through (v) TA534103 and TA703236

Qty. Rgd. Ill. No.

Part No.

Description

*NLA = No Longer Available

			in in
_			
	e-c ique	19 ELECTRIC ANTENNA #9124 #STC8040G	١
A TRACTICON AND A	65-	20 LINK LEAD #LRNA4G	
19 20	9124 STC8040G LRNA4G	ANTENNA, audio system, electric ANTENNA, audio system, electric, Genuine LINK LEAD, electric antenna, Genuine	
		Audio and Security	
	21 CD AUTOCHANK #AMR30530 UNDER HOOD SI #AMR2022	лтсн 25	EMOTE 1230G
21	AMR3053G	AUTOCHANGER ASSEMBLY, compact disc,	
22	AMR3722G	Genuine REMOTE UNIT, alarm, single button, Genuine	
23	STC961G	Through 1995 model year BATTERY, remote unit, Genuine Through 1995 model year;	
	YWX1012300	always change batteries in pairs G REMOTE UNIT, alarm, two button, Genuine	
24		From 1996 model year on	
	YWK10003L0	BATTERY, remote unit, Genuine From 1996 model year on	

Replacing antennas is more difficult than you might imagine. This job requires the removal of the inner fender splash shield. Check our website for complete instructions. Note- A manual antenna cannot be replaced with a power antenna, the radios are matched to the antennas.

Shop Online at www.AtlanticBritish.com

Qty. Rgd.



### **HEATING AND AIR CONDITIONING**



Engine (e) numbers: 35D = 3.9 liter, manual transmission, distributor ignition 36D = 3.9 liter, automatic transmission, distributor ignition 50D = 4.0 liter, electronic ignition Vehicle i.d. (v) numbers: RA = 1994 model year; SA = 1995 model year; TA = 1996 model year



BTR8726	HOSE, heater to valve	1
	Through (v) RA104738	
BTR8727	HOSE, valve to heater	1
	Through (v) RA104738	
BTR4016	HOSE, engine to valve	1
	Through (v) RA103486	
AWR1364G	HOSE, engine to valve, Genuine	1
	From (v) RĂ103487 to 104738	
BTR8725	HOSE, valve to engine	1
	Through (v) RA103486	
AWR1363G	HOSE, valve to engine, Genuine	1
	From (v) RA103487 to 104738	
PCH000100	HOSE, heater in/out	1
	From (v) RA104739 through 1995 model year	
PCH000110	HOSE, heater in/out	1
	From (v) 1996 model year on	
8880	HEATER HOSE KIT, H20 valve	*NLA
	(v) 1994 model year	
8882	HEATER HOSE KIT, without H20 valve	*NLA
	(v) 1994 through 1999 model year	
ННСК	CLAMP KIT, heater hoses	1
	Includes 8 clamps	-

VISA

7

8

9





*NLA = No Longer Available

**PRICES SUBJECT TO CHANGE.** Call for the Latest Pricing and Availability.

27

Heating

\$

Air

Conditionaing



Ill. No. Part No.	Description	Qty. Rqd.
	8 FRONT DOOR AC #AMR3382G #AMR3384G	TUATOR
<ul> <li>RTC6685G ALR2255G</li> <li>MXC3178G</li> <li>CWE10032LG</li> <li>MTC7593G MTC7592G</li> <li>MUC1822G</li> <li>AMR3382G AMR3384G</li> </ul>	DOOR HANDLE, exterior, front RH, Genuin DOOR HANDLE, exterior, front LH, Genuin GASKET, exterior door handle, front, Genu KEY, blank, Genuine Original style with rubber head DOOR LATCH ASSEMBLY, front RH, Genuin DOOR LATCH ASSEMBLY, front LH, Genuine DUST SEAL, front door latch, Genuine ACTUATOR, front door RH, Genuine ACTUATOR, front door LH, Genuine	e 1 iine 2 A/R e 1
9 REAR DOOR HANDLE HNXC12546 HMXC12556	Rear Door Handles	04G
<ul> <li>9 MXC1254G</li> <li>MXC1255G</li> <li>10 MXC3178G</li> <li>11 MTC9204G MTC9203G</li> <li>12 MUC1822G</li> <li>13 AMR3382G</li> </ul>	DOOR HANDLE, exterior, rear RH, Genuine Through (v) WA746541 DOOR HANDLE, exterior, rear LH, Genuine Through (v) WA746541 GASKET, exterior door handle, rear, Genui DOOR LATCH ASSEMBLY, rear RH, Genuine DOOR LATCH ASSEMBLY, rear LH, Genuine DUST SEAL, rear door latch, Genuine ACTUATOR, rear door, Genuine	ne 2
	14     FRONT     REGULA     #RTC38     #RTC38	314
14 RTC3814 RTC3815	REGULATOR, window, front door RH Through (v) SA137189 REGULATOR, window, front door LH Through (v) SA137189	1 1



PRICES SUBJECT TO CHANGE.

Call for the Latest Pricing and Availability

Shop Online at www.AtlanticBritish.com







Front Body Fittings



**Rear Panels** 1 REAR DOOR OUTER #MWC90840 #ALR8572G REAR QUARTER #MWC68040 #RTC6844G 1 MWC9084G DOOR OUTER PANEL, rear, RH, Genuine 1 Through 1995 model year; can be fitted to later models ALR8572G DOOR OUTER PANEL, rear, RH, Genuine 1 From 1996 model year on 2 MWC6804G REAR QUARTER PANEL, RH, Genuine 1 RTC6844G REAR QUARTER PANEL, LH, Genuine 1 **Rear Bumper** 8 END CAP BRACKET #ANR3025 #ANR3026 9 10 REFLECTOR REFLECTOR CLIP #AMR2330G #BTR7051G 6 STEP MAT REAR BUMPER #RTR94 #ANR2743 #DPB103910 7 END CAP 4 TREADSTRIP TREADSTRIP RIVET NR2989PMI #79086 BUMPER ASSEMBLY, rear, black ANR2743 3 1 DPB103910 BUMPER ASSEMBLY, rear, chrome 1 LSE models from (v) WA746542 on ANR2743FK *NLA FIXING KIT, Bumper Assembly, rear AWR2710PMDG TREADSTRIP, rear bumper, Genuine 1 From (v) SA118555 on 79086 RIVET, plastic, treadstrip, Genuine 5 8 6 BTR9434PMDG MAT, rear bumper step, Genuine 1 7 AWR2990PMDG END CAP ASSY, rear bumper, RH, Genuine 1 From (v) 1996 model year on AWR2989PMDG END CAP ASSY, rear bumper, LH, Genuine 1 From (v) 1996 model year on 8 ANR3025 BRACKET, end cap support, RH 1 BRACKET, end cap support, LH ANR3026 1 AMR2330G REFLECTOR, end cap, Genuine q 2 10 BTR7051G CLIP, reflector retaining, Genuine 2 11 ANR3196G PLUG, blanking tow hitch socket, Genuine 1 CARRIER ASSEMBLY, spare wheel, Genuine ALR5693G 12 1 BTR9438MUEG COVER, spare wheel, Silver, Genuine 13 1 14 BTR9901LAVG DECAL, spare wheel cover, 'LAND ROVER', Dark Grey, Genuine 1 15 LRNASE7MUKG DECAL, back door, 'SE7', Mid-Silver, Genuine 1 *NLA = No Longer Available

Ill. No

Part No.

Description

Ill. No. Part No. Description

Qty. Rgd.

Qty. Rgd.



Shop Online at www.AtlanticBritish.com



Ill. No.	Part No. D	escription	Qty. Rqd.
L	LOADSPACE COVER #STC78 LOSUCE	B 15 SCREW WASHER WAIDS201L WAIDS201L WAIDS201L WAIDS201L WAIDS201L WAIDS201L WAIDS201L TO TO TO TO TO TO TO TO TO TO	
S	eats	*Exiter 100	
a	nd ascia	19 COVER CATCH HBTR32646	
•	uoonu	20	
		ACCESS PANEL #AWR7000LNFG 22 CUPHOLDER #FJI000040LNFG	
12	STC7810SUCG	COVER, loadspace, Bahama Beige, Genuine	1
13	ESI100020SUC	Not vehicles fitted with rear air conditioning GMOUNTING SOCKET, loadspace cover,	
1/	MYCODOFELICC	Bahama Beige, Genuine From (v) VA730341 on	2
14	MXC8295SUCG	GRAB HANDLE, back door post, Bahama Beige, Genuine	1
	SH105201L	SCREW, grab handle to door post	4
	WA105001L	WASHER, plain	4
	MWC9275LOYG MWC9275SUCG		1 1
	BTR5709LNFG	SPEAKER GRILLE, subwoofer, Genuine	1
19	BTR3264G	CATCH, seat plinth cover, Genuine	2
20		For models fitted with CD player	2
	AWR7000LNFG LRN1292LMLG	ACCESS PANEL, seat box, Genuine RETAINER KIT, fascia, Genuine	2
		G CUPHOLDER ASSEMBLY, fascia, Genuine	1
	STC8030G	ROLLER BLIND KIT, car set of blinds with	
~ /	MMC775 CC / 22	fixings, Genuine	1
24	MWC//56SUCG	DOOR MAP POCKET, front left,	1
		Bahama Beige, Genuine From 1994 up to 1995 model year	1
	MWC7757SUCG	DOOR MAP POCKET, front right,	
		Bahama Beige, Genuine	1
	AWR2615LOYG	From 1994 up to 1995 model year DOOR MAP POCKET, front left, Granite,	
		Genuine	1
		From 1996 up to 1999 model year	-
	AWR2614LOYG	DOOR MAP POCKET, front right, Granite,	4
		Genuine From 1996 up to 1999 model year	1
	AWR2615SUCG	DOOR MAP POCKET, front left,	
		Bahama Beige, Genuine	1
	AMD261/CLICC	From 1996 up to 1999 model year	
	AWR2614SUCG	Bahama Beige, Genuine	1
		From 1996 up to 1999 model year	
		RETAINER, sun visor, Genuine	2
	BTR3088PMAG	MAT, for automatic console, Genuine	1
	LILIOUIPONNAG	MAT, for manual console, Genuine	1

#### Ill. No. Qty. Rgd. Part No. Description 24 DOOR MAP POCKET #MWC7756SUCG 26 #MWC7757SUCG CONSOLE MAT #AWR2615LOYG #AWR2614LOYG #BTR3088PMAG #AWR2615SUCG **#FIF100150PMAG** #AWR2614SUCG **Common Replacement Items for Discovery** I **Discovery I Replacement** Mirrors If you're an off-road enthusiast who pushes the limits of your Disco Iyou may be in need of new side or rear view mirrors. We have the genuine replacements you need to get your Disco I back up to snuff. Door Mirror - Right Hand (CRB108840G) Door Mirror - Left Hand (CRB108850G) Rear View Interior Mirror with Auto-Dim (AWR2146G) Rear View Interior Mirror w/ Manual Dim (STC4781G)



Discovery I Loadspace Cover Mount

Loadspace Cover Mount Bracket - (ESI100020SUCG)

Loadspace Protector - PVC Nylon (STC8144G)

### Discovery I Loadspace Cover (without rear a/c)

aquar for the Discourse Lin

We have replacement loadspace covers for the Discovery I in stock and in beige to match your interior. A horizontal vinyl "window shade" that keeps prying eyes from seeing what you've got loaded in the back.

Loadspace Cover - Discovery I (without rear a/c) (STC7810SUCG)

8