

AM26LS32

QUAD EIA-422/3 LINE



QUAD EIA-422/423 Line Receiver with Three-State Outputs

Motorola's Quad EIA–422/3 Receiver features four independent receiver chains which comply with EIA Standards for the Electrical Characteristics of Balanced/Unbalanced Voltage Digital Interface Circuits. Receiver outputs are 74LS compatible, three–state structures which are forced to a high impedance state when Pin 4 is a Logic "0" and Pin 12 is a Logic "1." A PNP device buffers each output control pin to assure minimum loading for either Logic "1" or Logic "0" inputs. In addition, each receiver chain has internal hysteresis circuitry to improve noise margin and discourage output instability for slowly changing input waveforms. A summary of AM26LS32 features include:

- Four Independent Receiver Chains
- Three–State Outputs
- High Impedance Output Control Inputs (PIA Compatible)
- Internal Hysteresis 30 mV (Typical) @ Zero Volts Common Mode
- Fast Propagation Times 25 ns (Typical)
- TTL Compatible
- Single 5.0 V Supply Voltage
- Fail–Safe Input–Output Relationship. Output Always High When Inputs Are Open, Terminated or Shorted
- 6.0 k Minimum Input Impedance





* Note that the surface mount MC26LS32D device uses the same die as in the plastic DIP AM26LS32DC device, but with an MC prefix to prevent confusion with the package suffix.



PIN CONNECTIONS

ORDERING INFORMATION

Device	Operating Temperature Range	Package
AM26LS32PC	T _A = 0 to 70°C	Plastic DIP
MC26LS32D*	$I_{A} = 0.070 C$	SO-16

© Motorola, Inc. 1995

MAXIMUM RATINGS

Rating	Symbol	Value	Unit
Power Supply Voltage	V _{CC}	7.0	Vdc
Input Common Mode Voltage	VICM	± 25	Vdc
Input Differential Voltage	VID	± 25	Vdc
Three–State Control Input Voltage	VI	7.0	Vdc
Output Sink Current	lo	50	mA
Storage Temperature	T _{stg}	– 65 to + 150	°C
Operating Junction Temperature	Тј	+ 150	°C

RECOMMENDED OPERATING CONDITIONS

Rating	Symbol	Value	Unit
Power Supply Voltage	Vcc	4.75 to 5.25	Vdc
Operating Ambient Temperature	ТА	0 to + 70	°C
Input Common Mode Voltage Range	VICR	- 7.0 to + 7.0	Vdc
Input Differential Voltage Range	VIDR	6.0	Vdc

ELECTRICAL CHARACTERISTICS (Unless otherwise noted, minimum and maximum limits apply over recommended temperature and power supply voltage ranges. Typical values are for $T_A = 25^{\circ}C$, $V_{CC} = 5.0$ V and $V_{IC} = 0$ V. See Note 1.)

Characteristic	Symbol	Min	Тур	Max	Unit
Input Voltage – High Logic State (Three–State Control)	VIH	2.0	-	-	V
Input Voltage – Low Logic State (Three–State Control)	VIL	-	-	0.8	V
$ \begin{array}{l} \mbox{Differential Input Threshold Voltage (Note 2)} \\ (-7.0 \ V \ \leqslant \ V_{IC} \ \leqslant \ 7.0 \ V, \ V_{IH} = 2.0 \ V) \\ (I_O = -0.4 \ mA, \ V_{OH} \ \geqslant \ 2.7 \ V) \\ (I_O = 8.0 \ mA, \ V_{OL} \ \leqslant \ 0.45 \ V) \end{array} $	VTH(D)			0.2 -0.2	V
Input Bias Current (V _{CC} = 0 V or 5.25) (Other Inputs at -15 V \leq V _{in} \leq +15 V) V _{in} = +15 V V _{in} = -15 V	IB(D)			2.3 -2.8	mA
Input Resistance (–15 V \leq V _{in} \leq +15 V)	R _{in}	6.0 K	-	-	Ohms
$ Input Balance and Output Level \\ (-7.0 V \leq V_{IC} \leq 7.0 V, V_{IH} = 2.0 V, See Note 3) \\ (I_O = -0.4 mA, V_{ID} = 0.4 V) \\ (I_O = 8.0 mA, V_{ID} = -0.4 V) $	Voh Vol	2.7		_ 0.45	V
Output Third State Leakage Current $(V_{I(D)} = + 3.0 \text{ V}, V_{IL} = 0.8 \text{ V}, V_{O} = 0.4 \text{ V})$ $(V_{I(D)} = -3.0 \text{ V}, V_{IL} = 0.8 \text{ V}, V_{O} = 2.4 \text{ V})$	loz			-20 20	μΑ
Output Short Circuit Current ($V_{I(D)} = 3.0 \text{ V}, V_{IH} = 2.0 \text{ V}, V_{O} = 0 \text{ V}, \text{ See Note 4}$)	los	-15	_	-85	mA
Input Current – Low Logic State (Three–State Control) (VIL = 0.4 V)	ΙL	-	-	-360	μΑ
Input Current – High Logic State (Three–State Control) (VIH = 2.7 V) (VIH = 5.5 V)	Чн			20 100	μΑ
Input Clamp Diode Voltage (Three–State Control) $(I_{IC} = -18 \text{ mA})$	VIK	-	_	-1.5	V
Power Supply Current (V _{IL} = 0 V) (All Inputs Grounded)	ICC	-	-	70	mA

NOTES: 1. All currents into device pins are shown as positive, out of device pins are negative. All voltages referenced to ground unless otherwise noted.
2. Differential input threshold voltage and guaranteed output levels are done simultaneously for worst case.
3. Refer to EIA-422/3 for exact conditions. Input balance and guaranteed output levels are done simultaneously for worst case.
4. Only one output at a time should be shorted.

AM26LS32

Characteristic	Symbol	Min	Тур	Max	Unit
Propagation Delay Time – DIfferential Inputs to Output (Output High to Low) (Output Low to High)	^t PHL(D) ^t PLH(D)			30 30	ns
Propagation Delay Time – Three–State Control to Output (Output Low to Third State) (Output High to Third State) (Output Third State to High) (Output Third State to Low)	^t PLZ ^t PHZ ^t PZH ^t PZL	- - - -	- - - -	35 35 30 30	ns

Figure 1. Switching Test Circuit and Wave for Propagation Delay Differential Input to Output





t_{TLH} – t_{THL} – 6.0 ns (10% to 90%) PRR – 1.0 MHz, 50% Duty Cycle





AM26LS32

OUTLINE DIMENSIONS



Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death Motorola was negligent regarding the design or manufacture of the part. Motorola and a registered trademarks of Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

How to reach us:

USA/EUROPE: Motorola Literature Distribution; P.O. Box 20912; Phoenix, Arizona 85036. 1–800–441–2447 JAPAN: Nippon Motorola Ltd.; Tatsumi–SPD–JLDC, Toshikatsu Otsuki, 6F Seibu–Butsuryu–Center, 3–14–2 Tatsumi Koto–Ku, Tokyo 135, Japan. 03–3521–8315

MFAX: RMFAX0@email.sps.mot.com - TOUCHTONE (602) 244–6609 INTERNET: http://Design-NET.com

 \Diamond

HONG KONG: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852–26629298



AM26LS32/D