

C-MOS BREAK SIGNAL DETECTOR
-TOP VIEW-



PIN No.	I/O	SIGNAL	PIN No.	I/O	SIGNAL	PIN No.	I/O	SIGNAL	PIN No.	I/O	SIGNAL
1	I	IN	12	O	GXT	23	O	ST	34	O	MCK
2	I	RES	13	O	XT2	24	O	DISA	35	-	NC
3	I	TEST	14	I	XT1	25	O	DISA	36	-	NC
4	-	NC	15	-	GND	26	O	OUT	37	-	NC
5	-	NC	16	-	VDD	27	-	NC	38	-	NC
6	-	NC	17	-	GND	28	-	NC	39	-	VDD
7	-	NC	18	-	NC	29	O	CK16	40	-	NC
8	-	NC	19	-	NC	30	-	NC	41	-	NC
9	-	NC	20	-	NC	31	-	NC	42	-	NC
10	-	NC	21	O	UP	32	O	MCK	43	-	NC
11	-	GND	22	O	DWN	33	-	GND	44	-	NC

