

POWER FACTOR CONTROLLER

- TOP VIEW -



COMPEN ; COMPENSATION

CURR ; CURRENT SENSE INPUT

DRIVE ; DRIVE OUTPUT

MULTI ; MULTIPLIER INPUT

VF ; VOLTAGE FEEDBACK INPUT

ZERO ; ZERO CURRENT DETECT INPUT

