Low Voltage PLL Clock Driver

The MPC956 is a 3.3V PLL based clock driver designed explicitly to support the MPC601 and MPC601+ microprocessor. The device synthesizes all of the current and future MPC601 processor frequencies from a 33.33MHz crystal source. The three processor clocks lag the BCLK's by one VCO period to ease system integration. For system architectures which support an asynchronous PCI bus a buffered copy of the 33.33MHz is provided. This output can be fanout further via the MPC903 to provide the PCI bus clocks.

- Provide PowerPC[™] 601 Clocks (66, 80 and 100 MHz)
- Support +2, +3 and +4 Bus Modes
- Fully Integrated PLL
- Output Frequencies Synthesized from Single 33.33MHz Crystal
- Output Frequency Up to 200MHz
- Output–Output Skew 500ps
- Provides Asynchronous PCI Clock
- Power Management Features
- 3.3V VCC
- 32-Lead TQFP Packaging
- ±150ps Cycle-to-Cycle PLL Jitter

The MPC956 provides a special power down mode for system power management. The scheme simplifies the design of a system which meets the Energy Star requirements. When asserted (driven to a logic HIGH) the Doze pin will seemlessly reduce all of the output frequencies of the chip. The reductions are implemented in a fashion to minimize power

while keeping enough speed to not hamper the performance to the end user. Because the frequency reduction is timed internally there is no need to halt the system to implement the power down mode.

The 4 select pins choose among 14 possible ouput configurations. The configurations were chosen to represent the most common PowerPC 601 and PowerPC 601+ system applications. The outputs are synthesized from a 33.33MHz crystal, this crystal input is also buffered and provides a an output for use with an aynchronous PCI bus.

The MPC956 works from a 3.3V supply and is packaged in a 32 lead TQFP to optimize performance and board space requirements.

PowerPC is a trademark of International Business Machines Corporation.





8/95

MPC956 LOGIC DIAGRAM





MPC956 OUTPUT FREQUENCIES

Select	2xPClk	2xPClk, Doze	PCIkEn	BCIkEn, BCIkn	PCIkEn,BCIkEn, BCIkn, Doze
0	133.33	33.33	66.66	33.33	16.66
1	160	40	80	40	20
2	160	40	80	26.67	20
3	200	50	100	50	25
4	200	50	100	33.33	25
5	240	60	120	60	30
6	240	60	120	40	30
7	240	60	120	30	30
8	266.66	66.66	133.33	66.67	33.33
9	266.66	66.66	133.33	44.44	33.33
10	266.66	66.66	133.33	33.33	33.33
11	300	75	150	75	37.50
12	300	75	150	50	37.50
13	300	75	150	37.50	37.50

*Current product only specified for 2xPClk of ≤200MHz.

DC CHARACTERISTICS ($T_A = 0^\circ$ to 70° C)

Symbol	Characteristic	Min	Тур	Max	Unit	Condition
V _{DD}	Power Supply Voltage	3.0		3.8	V	
VIL	Input LOW Voltage			0.3V _{DD}	V	
VIH	Input HIGH Voltage	0.7V _{DD}		V _{DD}	V	
VOH	Output HIGH Voltage	V _{DD} -0.4			V	
VOL	Output LOW Voltage			0.4	V	
C _{IN}	Input Capacitance			4.5	рF	

AC CHARACTERISTICS (T_A = 0° to 70°C, V_{CC} = 3.3V ± 0.3 V)

Symbol	Characteristic	Min	Тур	Max	Unit	Condition
fXtal	Input Crystal Frequency	20		40	MHz	
f _{max}	Maximum Output Frequency 2xPLCK PCLKEN BCLK			200 100 50	MHz	1.4V, Z ₀ = 50Ω
^t dc	Output Duty Cycle 2xPCLK Other	35 45		65 55	%	1.4V, Z ₀ = 50Ω
^t jitter	PLL Cycle-to-Cycle Jitter (Peak-to-Peak)			±150	ps	Note 2
^t skew	Output–to–Output Skew BLCK 2xPCLK, PCLKEN, BCLKEN		300 300	500 500	ps	1.4V, Z ₀ = 50Ω
^t per	Minimum Output Period 2xPCLK	4.85			ns	Fout2xP = 200MHz
^t pw	2xPCLK Pulse Width	1.75			ns	Fout2xP = 200MHz
^t pskew	BCLK to 2xPCLK Skew	1/f _{VCO} -900		1/fvco	ps	Fout2xP ≤ 200MHz
^t delay	Time Delay 2xPCLK to BCLKEN	50		550	ps	Note 1, 1.4V, $Z_0 = 50\Omega$
t _r , t _f	Output Rise/Fall Time			0.8	ns	1.0 to 1.8V, 1.4V, $Z_0 = 50\Omega$
^t LOCK	PLL Lock Time			10	ms	
^t PZL ^{, t} PZH	Output Enable Time			20	ns	
^t PLZ ^{, t} PHZ	Output Disable Time			20	ns	

Guaranteed to meet setup/hold times for the PowerPC[™] 601 processor.
Guaranteed but not tested.



Figure 1. Timing Diagrams for Select Options (For clarity, processor clock lag not shown)





5



Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and are registered trademarks of Motorola, Inc. Motorola, linc. is an Equal Opportunity/Affirmative Action Employer.

How to reach us:

USA/EUROPE: Motorola Literature Distribution; P.O. Box 20912; Phoenix, Arizona 85036. 1–800–441–2447 JAPAN: Nippon Motorola Ltd.; Tatsumi–SPD–JLDC, Toshikatsu Otsuki, 6F Seibu–Butsuryu–Center, 3–14–2 Tatsumi Koto–Ku, Tokyo 135, Japan. 03–3521–8315

MFAX: RMFAX0@email.sps.mot.com -TOUCHTONE (602) 244-6609 INTERNET: http://Design-NET.com HONG KONG: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852–26629298

🕭 MOTOROLA

