

C-MOS MULTI-PURPOSE REMOTE CONTROL TRANSMITTER

-TOP VIEW-



INPUT

AC ; ALL CLEAR (LOW VOLTAGE DETECTOR)
 KI0 - KI3 ; INPUT PORT
 OSC-IN ; OSCILLATOR CONNECTED
 S-IN ; SERIAL

OUTPUT

OSC-OUT ; OSCILLATOR CONNECTED
 REM ; REMOTE CONTROL CORRESPOND
 S-OUT ; TRANSMITTING INDICATION

INPUT/OUTPUT

KI/O0 - KI/O7 ; INPUT/OUTPUT PORT

