Z8E000/001

ERRATA

OT001300-Z8X0599

STOP-MODE RECOVERY OPERATION

The operation of the stop-mode recovery pin on the Z8E000 and Z8E001 devices differs from the recovery pin on the Z8ICEXXXZEM emulator. The devices require a High-to-Low transition to wake up the Z8 from STOP mode and enter it into RESET mode. A subsequent Low-to-High transition commences code execution. The emulator requires only a High-to-Low transition to wake up the Z8 and commence code execution.


NOTE: For details on the parameters in the figure below, please see ZiLOG technical publications <u>Z8E000</u> and/or <u>Z8E001</u>.

ADDITIONAL INFORMATION

The following documents provide additional information on Z8Plus devices:

- Product Specifications:
 - <u>Z8E000</u>
 - <u>Z8E001</u>
- User Manual:
 - Z8Plus User Manual
- Emulator Specifications:
 - Z8ICE000ZEM
 - Z8ICE010ZEM

E000/E001



Z8ICEXXXZEM

