AMPEREX MERCURY VAPOR RECTIFIER 866-A

FILAMENT

A.C. Voltage .	•	•	•	•	•	•	•	•	2.5
Current (amperes)	•	•	•	•		•	•	•	5.0
Preheating Period	(Sec	ond	s)*				•		30

^{*}Before plate voltage is applied.

MAXIMUM RATINGS

For Operation At Supply Frequency
Up to
150 Cycles
With Condensed Mercury
Temperature Range

For Operation At Supply Frequency Up to 1000 Cycles With Condensed Mercury Temperature Range

	25°C. to 60°C.	25°C. to 70°C.	25°C. to 70°C.
Peak Inverse Voltage	. 10000	2000	5000
Peak Plate Current (ampere) .	. 1.0	2	1.0
Average Plate Current (ampere)*	25	0.5	.25
Approx. Tube Voltage Drop	. 10	10	10

^{*}Averaged over period of 10 seconds.


MAXIMUM OUTPUTS IN TYPICAL CIRCUITS

	A.C. Input Volts R.M.S.	D.C. Output Volts to Filter	Max. D.C. Load Current Amperes
Single-Phase Full Wave (2 Tubes)	3535*	3180	.5
Single-Phase Full Wave Bridge (4 Tubes)	7070†	6360	.5
Three-Phase Half Wave (3 Tubes)	4080#	4780	.75
Three-Phase Double Y-Parallel (6 Tubes)	4080‡	4780	1.5
Three-Phase Full Wave (6 Tubes)	4080‡	9570	.75

^{*}Per Tube. †Total. ‡Per Leg.

NOTE: For Out-Of-Phase Filament Excitation information see "Maximum Peak Plate Current" and "Maximum Average Plate Current", pp. 3 and 4, "General Information and Application Notes" section, "Mercury Vapor High Voltage RECTIFIER TUBES".





AMPEREX

866-A

†Ratio Primary Kva D.C. Output-Kw	† Ratio Secondary Kva D.C. Output-Kw	Ripple Voltage (Rms)	Ripple Frequency	I Average	E Inverse	E Average	Conditions assumed for following relations 1. Sine-Wave Supply 2. Balanced Phase Voltages 3. Zero Tube Drop 4. Pure Resistance Load 5. No Filter Used NOTE: All rectifier filaments supplied by single phase transformers, with secondaries insulated for voltages greater than the Maximum Peak Inverse Voltage.	RECTIFIER CIRCUIT
1.11	1.57	48.3%	2 X Supply Freq.	.636 I max	3.14 E avg	.450 E rms .318 E max	SUPPLY LOOP FIG. 1	SINGLE PHASE FULL-WAVE 2 TUBES
1.11	1.11	48.3%	2 X Supply Freq.	.636 I max	$1.57~E~\mathrm{avg}$.900 E rms .636 E max	FIG. 2 Envy. SUPPLY FRMS FRMS	SINGLE PHASE FULL-WAVE 4 TUBES
1.21	1.48	18.3%	3 X Supply Freq.	.827 I max	$2.09~E~\mathrm{avg}$	1.170 E rms .827 E max	FIG. 3	THREE PHASE HALF-WAVE
1.05	1.48	4.2%	6 X Supply Freq.	1.91 I max	2.09 E avg	1.170 E rms .827 E max	FIG. 4	THREE PHASE
1.05	1.05	4.2%	6 X Supply Freq.	.955 I max	$1.045~E~\mathrm{avg}$	2.34 E rms 1.65 E max	FIG. 5	THREE PHASE FULL-WAVE

† These ratios assume that a choke input filter is used to maintain the output current substantially constant.